Surveyor Rajsu | REF: ATLh | 20849

# ASSIGNMENT

From: | Date: 07/02/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: EZ 39664

at Workshop m/s Volkswagen

of 1 Kamping Ampat Off Macpherson Rd

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh:

(Policy Condition) 5pm Owner waiting

Remark: The veh had commenced its repair at the time of inspection.

| N/S | O/S |
|---|---|
| | |

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: EZ 39664 Yr Regn: 2015 APR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Volkswagen JETTA 1.4 TSI cc 1390

Colour: GRey A/C: Insured / Std / NI / NA

Sp.Reading: 100055 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No. WVWZZZ1KZEM058795

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

| Front | | Rear | |
|---|---|---|---|
| R/Bal. | 6 mm | R/Bal. | 6 mm |
| L/Bal. | 6 mm | L/Bal. | 6 mm |
| D.O.A. | 05/02/18 | D.O.I. | 07/02/18 |

Survey held at Volkswagen KL Ampat

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

Date/Time File Pass to? 1 | ☐ : Preli. Report | ☐ : Final Report

Date/Time File Return to? 2

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp $ | ☐ Interview $ | ☐ Tech Insp $ | ☐ Assessment $

Survey Fee | Transportation | Photos | Other | TOTAL

Report Format :

Lump Sum / I.B.I: $