Surveyor: Yeol. REF: ASM

ASSIGNMENT

From: Date: 22/02/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SCE 899L

at Workshop m/s: Kah Motor

of: 15 Ubi Road 4

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record): 10-30 am owner waiting

Make of Veh: Mr Liew

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: $90K.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS / wp

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SCE 899L Yr Regn: 29 Sep 2016

Type: M Car / M Cycle / Buse / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Civic c.c.: ~~1.7~~ 1.5 1597

Colour: purple A/C: Insured / Std / Nil / NA

Sp Reading: 13837 T/Radio: Insured / Std / Nil / NA

Eng No:

C/No: ~~MRH~~ MRHFC5650GT000354

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size F: 215/55 R16

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Hankook

Front		Rear	
R/Bal.	? mm	R/Bal.	? mm
L/Bal.	? mm	L/Bal.	? mm

D.O.A.: D.O.I.: 22-02-18. 10:30AM

Survey held at: W/S

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction

Date/Time File Pass to: : Preli. Report

: Final Report

Date/Time File Return to:

Report Format:

Lump Sum / I.B.I. / S

Days Of Repair:

Resurvey No. of Trip:

Add Fee: Site Insp. / S

Interim / S

Tech. / S

Meeting / S

Survey Fee

Transportation

Photos

Other

Total