Surveyor: Tayfikh | REF: ASM (AXA) 33741 Tina3 | (W)

ASSIGNMENT

From: | Date: 13 03 2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBD 3561H

at Workshop m/s Goldbell

of 29 Tanjong Penjuru

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh:

(Policy Condition) 4pm owner waiting

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: | Consistent? : Yes or No

GIA / PR Seen: | Consistent? : Yes or No

Est. Repairs: days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: GBD 3561 H | Yr Regn: 2014 / Sep.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mitsubishi Canter | c.c 2998

Colour white | A/C: Insured / Std / NI / NA

Sp.Reading 22006. | T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: FEA01KA00495

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : NIL / S/Rim / STD A/Rim or

Tyre Size: F: 185/75R15

R: " "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6/6 mm
L/Bal.	6 mm	L/Bal.	6/1. mm
D.O.A.		D.O.I.	13/3/18@4pm

Survey held at 29 Tanjong Penjuru

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? [ ] : Preli. Report

1) [ ] : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee: [ ] : Site Insp ($) __S + RS __SI

[ ] : Interview ($) Photos

[ ] : Tech. Invs ($) Others

[ ] : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

TOTAL