(08/11/18) Surveyor: Tanjith | REF: ALG | 3859/71223 - (e)

ASSIGNMENT

From: | Date: 27.02.2018

Estimated Cost:

OD / (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKT 8812K

at Workshop m/s Performance

of 303 Alexandra Rd

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: | Consistent? : Yes or No

GIA / PR Seen: | Consistent? : Yes or No

Est. Repairs: days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: | Person Contacted: Inthiran. | Vehicle: IN / OUT

Veh No: SKT8812K. | Yr Regn: 2014 / Oct

Type: (M.Car) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: BMW 740 | c.c 2979

Colour Blue | A/C: Insured / Std / NI / NA

Sp.Reading 56617 | T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBAYE42040DD87363

Gen. Cond: (Good) / Fair / Poor / Burnt

Steering: (Inorder) / Jammed / Leaked / Burnt or

Brake: (Inorder) / Jammed / Leaked / Burnt or

Modi : Nil / (S/Rim) / STD A/Rim or

Tyre Size: F: 275/40R19

R: 〃 〃

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / (PIR) / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	27/2/18 01/30

Survey held at PML.

Des. of Damages : Frt / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? 1) ☐ : Preli. Report ☐ : Final Report

Date/Time, File Return to? 2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation: ___S + RS ___SI

Add Fee: ☐ : Site Insp ($) ☐ : Interview ($) ☐ : Tech. Invs ($) ☐ : Weekend ($)

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: ($)