Zam REF: 60114

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s: 90616581

of:

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| N/S | O/S |
|---|---|
| | |

Bal. or Market Value: 66k-

IDAC Accident Rpt m: Consistent? / Yes or No

GIA / PR Seen: Consistent? / Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Veh.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKA 94654 Reg: 2011 APR

Type: (M.Car) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Jaguar XF 3.0 V6 cc: 2967

Colour: BLACK A/C: Insured / Std / NIL / N.A

Sp.Reading: 148478 T.Radio: Insured / Std / NIL / N.A

Eng No:

C No: SAJAC05D9BPR97086

Gen Cond: Good / Fair / Poor / Burnt

Steering: (Normal) / Jammed / Leaked / Burnt or

Brake: (Normal) / Jammed / Leaked / Burnt or

Modi: NIL / S.Rim / STD A/Rim or

Tyre Size: F: 245/45ZR18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / (MI) / OHTSU / PIR / SUMI / TOYO / YOKO or

| Front | | Rear | |
|---|---|---|---|
| R.Bal. | 6 mm | R.Bal. | 6 mm |
| L.Bal. | 6 mm | L.Bal. | 6 mm |
| D.O.A. | 22/02/18 | D.O.A. | 27/02/18 |

Survey held at: Mova (PY)

Des. of Damages: (F) / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

| Date | Time | Action / Instruction |
|---|---|---|
| 2/3/18 | | Revert vehicle T/L by merimen |
| | | Rasul, Pls ask repairer to savage the airbag ECU if the car is repair. |
| 2/3/18 | | Submit uneconomical T/L |
| 5/3/18 | | @10spm Gerald call up want us to revert LS $15k |

RECEIVED 02 MAR 2018

Date/Time File Pass to: Preli. Report: Final Report:

Days Of Repair: 8

Resurvey No. of Trip: 1

Date/Time File Return of:

11/5- typist

Add Fee: Site Insp. $ Interpreter $ Tech. Insp. $ Reassessment $

Report Format: merimen

Lump Sum / I.B. $ LS $15000/2

Surv. Fee: 710+102

Reassessment: 50

50

53

580 +10

GSP 12/3/18

1005+10 = 1015

4/3 36x15=540 170+540=710 710x20%=102