創 CHARN'S CUSTOMCRAFT

NTUC/AIG(SLT4361T)

DOA: 12/02/2018@1250

AIG ASIA PACIFIC INSURANCE PTE LTD

ATTN: THE MOTOR CLAIMS DEPT

LKK Auto Consultants hence notify
the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- 01/02/2018
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

THIRD PARTY CLAIM
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SKM 7007 L - TOYOTA CAMRY 2.0 AUTO ABS AIRBAG
CHASSIS NO: MR053BK4107005404 (2007)

Qty	Description		Amount
1 pc	Rear boot	$	863.20
1 pc	Rear boot emblem 'CAMRY'	$	66.80
1 pc	Rear boot logo	$	71.60
1 pc	Rear boot emblem '2.0'	$	39.90
9 pcs	Rear boot sponge clips @ $3.60	$	32.40
1 pc	Rear boot lock	$	378.50
1 pc	Rear bumper	$	664.90
1 pc	Rear bumper retainer LH	$	60.30
1 pc	Rear bumpre retainer RH	$	60.30
1 pc	Rear end panel	$	602.10
1 pc	Rear end panel top garnish	$	383.30
		$	3,223.30
	LESS 25%	$	805.83
		$	2,417.47
1 set	Reverse sensor (S/NETT)	$	200.00
	Check wiring	$	40.00
	Remove necessary parts; jacking panel beating, repair and straighten rear inner panel, rear end panel, rear boot, rear bumper and spare tyre compartment.	$	800.00
	Putty and respray rear inner panel, rear end panel, rear boot, rear bumper and spare tyre compartment.	$	800.00
		$	4,257.47
	ADD 7% GST	$	298.02
		$	4,555.49

Note: The above is an estimate only. IF other parts requested
during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT