Surveyor: Tanjiki | REF: AXA

ASSIGNMENT

From: | Date: 5/3/18

Estimated Cost:

OD / TP / N/S / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKB 4008L

at Workshop m/s: Hong Seh

of: 10 Fourth Lok Yang Road

Insured:

Policy No:

Claims No:

Sum Insured: | Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 4163,000

IDAC Accident Report: | Consistent? : Yes or No

GIA / PR Seen: | Consistent? : Yes or No

Est. Repairs: days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Date: | Person Contacted: | Vehicle: IN / OUT Sam.

Veh No: SKB4008L | Yr Reg: 2011 May.

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Maserati Granturismo 4.2 :: 4244

Colour: white | A/C: Insured / Std / Nil / NA

Sp Reading: 76599 | T Radio: Insured / Std / Nil / NA

Eng No:

C No: ZAMGH45C000058269.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / Sport / STD A/Rim or

Tyre Size: F: 245/40R19

R: 〃

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PR / SUMI / TOYO / YOKO or

Front		Rear	
R.Bal: 6	mm	R.Bal: 6	mm
L.Bal: 6	mm	L.Bal: 6	mm
D.O.A:		D.O.: 6/3/18 e1630	

Survey held at: Hong Seh

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S . U/C

The U/C / Chassis frame / Body Structure affected due to collision

Date	Time	Action / Instruction
		0448 H

Date/Time File Pass to: | ☐ : Preli. Report | ☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Surveyor Fee:

Transportation:

Date/Time File Return to:

Add Fee: ☐ Site Insp. $ | ☐ Interim $ | ☐ Tech. $ | ☐ Meeting $

Report Format:

Lump Sum / N.B. $