Surveyor Rajne | REF: AXA | Ref: 18004347/Rjs3 | C 77C541

ASSIGNMENT

From: | Date: 07/03/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBC 6856T

at Workshop m/s Ban Choon

of Blk 3 Pioneer Rd North #01-15

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh:

after 12pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: | Consistent? : Yes or No

GIA / PR Seen: | Consistent? : Yes or No

Est. Repairs: days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No. GBC 6856T | Yr Regn 2013 Jun

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA DYNA 15U 3.0 | c.c 2982

Colour WHITE | A/C Insured / Std / NI / NA

Sp.Reading 196561 | T Radio Insured / Std / NI / NA

Eng/No:

C/No: JTFAT354 80K 202351

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/75R15

R: 155R12C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	5 mm
L/Bal.	6 mm	L/Bal.	5 mm
D.O.A.	26/02/18	D.O.I.	07/03/18

Survey held at Ban Choon

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

1)

Date/Time File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp $

☐ : Interview $

☐ : Tech. Invs $

☐ : Weekend $

Report Format :

Lump Sum / I.B.I: $

Survey Fee:

Transportation

Photos

Others

TOTAL