COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

Arig Asia - LSum TS

VEHICLE NO : SHD 4108G **DATE 6/3/2018**

MAKE :

LKK - Kalvin

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid Sonata Plate			$ 43.60	
	Boot Lid Hyundai Plate			$ 24.20	
	Boot Lid 'H' Emblem			$ 26.10	
	Boot Lid CRDI Plate			$ 22.70	
	Boot Lid Lamp (LH) ×			$ 230.20	
	Rear Bumper			$ 578.40	
	Rear Bumper Reinforcement ?			$ 483.30	
	Rear Bumper Clip			$ 22.00	
	Rear Bumper Sponge			$ 137.40	
	Rear Bumper Under Cover			$ 185.80	
	Rear Bumper Protector (LH)			$ 38.00	
	Tail Lamp (LH) ?			$ 344.00	
	Tail Lamp Quarter Panel (LH) × repair			$ 93.80	
	Rear Panel × repair			$ 391.80	
	Rear Panel Garnish ?			$ 95.80	
	Rear Fender (LH) × repair			$ 1,935.90	
	Rear Fender Inner Lining (LH) ×			$ 74.10	
	Rear Windscreen Moulding ×			$ 60.00	
	SUB TOTAL			**$ 4,787.10**	
	LESS 20%			$ 957.42	
	DISCOUNTED TOTAL			**$ 3,829.68**	
	Boot Lid Comfort Logo & Tel No. Sticker			$ 30.00	**Nett**
	Rear Bumper Reverse Sensor			$ 135.70	**Nett**
	Rear Bumper Rubber Mat			$ 50.00	**Nett**
	Rear Fender Comfort Sticker (LH)			$ 30.00	**Nett**
	Rear Windscreen Sealant ×			$ 46.00	**Nett**
				$ 291.70	
	Labour Charge				
	Panel Beating			$ ~~1,200.00~~	600
	Spray Painting Charge			$ ~~800.00~~	720
	Wiring Charge			$ ~~50.00~~	×
	Tuff Kote			$ ~~50.00~~	×
	Remove/Refix Cushion & Upholstery Rear			$ ~~150.00~~	50
	Remove/Refix Rear Windscreen Glass			$ ~~120.00~~	×
	Remove/Refix Reverse Sensor			$ ~~120.00~~	20
	TOTAL LABOUR			**$ 2,490.00**	
	ESTIMATE TOTAL			**$ 6,611.38**	

Kalvin (LKK)
6/3/18 14 Jobs
3 Days
4/5
After Repair photo

LKK Auto Consultants Pte Ltd
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.