COMFORTDELGRO ENGINEERING PTE LTD

AIG

VEHICLE NO : SH 9943C   DATE 7/3/2018 10:37

MAKE   :

Jumani

MODEL   : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper			$ 578.40	
	Rear Bumper Clip			$ 22.00	
	Rear Wheel Hup-Cap (RH)			$ 145.00	
	Front Door (RH)			$ 1,345.00	
	Rear Door (RH)			$ 1,294.70	
	Rear Fender (RH)				
	SUB TOTAL			$ 3,385.10	
	LESS 20%			$ 677.02	
	DISCOUNTED TOTAL			$ 2,708.08	
	Rear Bumper Advertisement Logo			$ 50.00	Nett
	Rear Bumper Rubber Mat			$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH)		$ 100.00	$ 200.00	Nett
	Rear Door Advertisement Logo (RH)			$ 100.00	Nett
	Front Door Coloured Comfort Logo (RH)			$ 75.00	Nett
	Front Door Advertisement Logo (RH)			$ 100.00	Nett
	Front Fender Advertisement Logo (RH)			$ 100.00	Nett
				$ 675.00	
	Labour Charge				
	Panel Beating			$ 1,000.00 *600*	
	Spray Painting Charge			$ 1,000.00 *720*	
	Wiring Charge			$ 50.00 *x*	
	Tuff Kote			$ 70.00 *20*	
	Towing Fees			$ 50.00	
	Remove/Refix Reverse Sensor			$ 120.00 *x*	
	Transfer of Door			$ 160.00 *100*	
	TOTAL LABOUR			$ 2,450.00	
	ESTIMATE TOTAL			$ 5,833.08	

Kalvin / LKK

7/3/18 1045hrs.

3 Days

4/s

After Repair photos.

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

6553 1111
SPARK Assist
Recovery · Towing · Accident

Appointed Partners

JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition

1. Date: 06-03-18	Time Received: 0235

2. ☐ New   ☐ SPARK Kakis

Name of Customer : MOHD SALIM

Contact No. : 86178678

Vehicle No. : SH9943C

Make / Model / Colour : SONATA

Email :

3. Vehicle Type:
- ☐ Private
- ☑ Taxi (CTPL/CCPL)
- ☐ Fleet
- ☐ STK (Boon Lay)

5. Nature of Service:
- ☐ Jumpstart
- ☐ Recovery
- ☐ Change Tyre / Battery

4. Type of Towing:
- ☑ Normal Tow
- ☐ King Dolly
- ☐ Flat Bed
- ☐ Crane-up

6. Parts Replaced/Remarks:

7. Location: 100 JURONG WEST AVE1

9. Preferred Workshop:
- ☐ Braddell
- ☑ Loyang
- ☐ Pandan
- ☐ Sin Ming
- ☐ Sungei Kadut
- ☐ Ubi
- ☐ Senoko
- ☐ Komoco (UBI / Leng Kee)
- ☐ Cycle & Carriage (PD)
- ☐ Others:

8. Vehicle Tow - In Workshop:
- ☐ Smoky Exhaust
- ☐ Wheel Jammed
- ☐ Overheating
- ☐ Steering Faulty
- ☐ Brake Faulty
- ☐ Alternator Faulty
- ☐ Starting Problem
- ☐ Loss Power
- ☑ Accident
- ☐ Engine Stalled
- ☐ Return Taxi

10. Odometer Reading : 526826

Fuel Level : | F | 1/4 | 1/2 | 3/4 | E |

11. Radio / CD Player
- ☐ OK
- ☐ Faulty
- ☐ Not tested

Job Attended

12. Tow Truck / Recovery Van : ☐ VRS ☑ QA ☐ STD ☐ TZ ☐ IRS ☐ OTHERS

Name of Driver : BASI

Vehicle No. : YSS469A

Time Dispatch : 0235

Time of Arrival : 0307

Time Completed :

FRONT

LEFT SIDE / RIGHT SIDE

REAR

\# : Cracked   X : Dented
/ : Scatched   O : Missing

Signature of Customer

Cash Invoice Details (if applicable)

13. Cash Invoice No. :

Customer Acknowledgement

a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.

b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.

c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

06-03-18	0307	
Date	Time	Signature of Customer

14. WORKSHOP

Name of Attending Staff/Guard	Date & Time of Arrival	Signature of Attending Staff/Guard

CUSTOMER'S COP