	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALVAGE%	PART PRICE(NET)	ACTIO (PART
		8	1			FRONT WHEEL ARCH LH			Damaged	165.44				165.44	Revie
		9	1			REAR DOOR ARCH LH			Damaged	88.06				88.06	Revie
		10	1			REAR WHEEL ARCH LH			Damaged	99.25				99.25	Revie
		11	8			WHEEL ARCHCLIP			Necessary	1.56				12.48	Revie
		12	1			FRONT DOOR GLASS LH			Damaged	157.13				157.13	Revie
		13	1			FRONT DOOR HANDLE LH			Damaged	134.12				134.12	Revie

Labour

Add Approve Deny

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	F
		1		TO REPLACE WING MIRROR ASSY LH, TO REPAIR ALL REAR FENDER LH, FRONT DOOR LH AND FRONT FENDER LH AREAS AFFECTED BY THE ACCIDENT.	2520	0	0	Reviewing		
		2		TO RESPRAY REAR FENDER LH, REAR DOOR LH, FRONT DOOR LH, FRONT FENDER LH AND WING MIRROR COVER LH.	3600	0	0	Reviewing		
		3		TO CARRY-OUT BODY CAVITY PRESERVTION.	150	0	0	Reviewing		
		4		TO REMOVE & REFIT CARPET & TRIMS ON THE REAR LH SECTION TO GIVE WAY TO THE REPAIR ON THE REAR LH SECTION.	840	0	0	Reviewing		

Detailed Assessment

Inspection Date *

03/19/2018

Total Loss

Yes **No**

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

700

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair

Steering (Serviceable)

Yes **No**

Footbrake (Serviceable)

Yes **No**

Handbrake (Serviceable)

Yes **No**

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

195/55R16

Rear Tyre Size

195/55R16

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY	Make
POLICY INFORMAT...	MINI
ASSESSMENT INFO...	MINI

CATEGORY	Model
POLICY INFORMAT...	ONE 1.2
ASSESSMENT INFO...	ONE 5DR HB 1.2 A/T D/AB ABS DSC

CATEGORY	Type
POLICY INFORMAT...	
ASSESSMENT INFO...	

CATEGORY	Type of Paint
POLICY INFORMAT...	
ASSESSMENT INFO...	

CATEGORY	Chassis No
POLICY INFORMAT...	WMWXS120202E79666

CATEGORY	Date of Birth
FNOL INFORMATI...	
POST SURVEY INF...	mm/dd/yyyy

CATEGORY	Age
FNOL INFORMATI...	
POST SURVEY INF...	

CATEGORY	Occupation
FNOL INFORMATI...	
POST SURVEY INF...	

CATEGORY	Education Qualification
FNOL INFORMATI...	
POST SURVEY INF...	

CATEGORY	Driving Experience
FNOL INFORMATI...	
POST SURVEY INF...	

CATEGORY	Driver License #

Accelerated
workshop survey

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Messages Invoices History Documents

Assessment Metrics Notes Add

Additional Instructions

Wkshop: Trans Eurokars Excess: $700 Survey
WP

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
WANG Peter	3/16/18 3:32 PM	10771.11	10771.11	Open	Share	Clone

Accelerated
workshop survey

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Messages Invoices History Documents

Assessment Metrics Notes

Additional Instructions

Wkshop: Trans Eurokars Excess: $700 Survey
WP

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Merimen	
DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (OD)	June 5, 2018
WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (OD)	June 5, 2018