English (default) LKK AUTO CONSULTANTS PTE LTD (TP)

SERVICE REQUESTS MESSAGES CLAIMS

			PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
			REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM.	60	0	0	Reviewing		
		6	REMOVE & REFIX FRT BUMPER ASSY HEADLAMPS, GRILLE, RADIATOR & MOTOR, FRT FENDERS, CUT, WELD & RENEW FRT SUPPORT PANEL, KNOCK & REPAIR FRT LH FENDER & REALIGN THE SAME.	600	0	0	Reviewing		
		7	TO PUTTY & RESPRAY ON FRT PORTION.	540	0	0	Reviewing		
		8	PUTTY & RESPRAY ON FRT & REAR RH DOORS, TAILGATE, REAR BUMPER, REAR RH FENDER, COMPARTMENT & ALL AFFECTED AREA.	1300	0	0	Reviewing		
		9	RUSTPROOFING	120	0	0	Reviewing		
		10	REMOVE & REFIX REAR EXHAUST & CHECK LEAKING.	60	0	0	Reviewing		
		11	TO MOUNT ON CAR-O-LINER, TO REALIGN CHASSIS	250	0	0	Reviewing		

English (default) LKK AUTO CONSULTANTS PTE LTD (TP)

SERVICE REQUESTS MESSAGES CLAIMS

				PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
				FRONT GRILLE CLIPS			Necessary	3.7		20		11.84	Reviewing	
	13	1		AIR-CON CONDENSER			Bent	747.8		20		598.24	Reviewing	
	14	1		RADIATOR			Bent	1302.9		20		1042.32	Reviewing	
	15	1		REAR TAILGATE			Bent	1282.8		20		1026.24	Reviewing	
	16	1		TAILGATE LOGO			Necessary	25.7		20		20.56	Reviewing	
	17	1		TAILGATE EMBLEM (FREED)			Necessary	42.1		20		33.68	Reviewing	
	18	1		REAR WINDSCREEN GLASS MOULDING			Necessary	151.8		20		121.44	Reviewing	
	19	1		REAR BUMPER			Bent	490.3		20		392.24	Reviewing	
	20	1		REAR BUMPER RH SIDE RETAINER			Damaged	28		20		22.4	Reviewing	
	21	6		REAR BUMPER CLIPS			Necessary	3.7		20		17.76	Reviewing	
	22	1		RH TAILLAMP			Cut	458.1		20		366.48	Reviewing	
	23	1		REAR RH TAILLAMP PANEL			Bent	210.3		20		168.24	Reviewing	
	24	1		REAR PANEL			Bent	342.9		20		274.32	Reviewing	
	25	1		REAR PANEL INNER TOP GARNISH			Serviceable	0		20		0	Reviewing	
	26	1		REAR RH FENDER			Buckled	1294.5		20		1035.6	Reviewing	

English (default) LKK AUTO CONSULTANTS PTE LTD (TP)

SERVICE REQUESTS MESSAGES CLAIMS

ASSESSMENT INFORMATION

0

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		mm/dd/yyyy
Address	Singapore	
Address type	Personal Correspondence	
Gender	Unknown	
Marital status	Unknown	
Identification #	TBC	

English (default) LKK AUTO CONSULTANTS PTE LTD (TP)

SERVICE REQUESTS MESSAGES CLAIMS

	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	November 15, 2018
From LKK_MV.tif	Letters and Correspondence	Investigator / Adjustor	LOH Cynthia	July 16, 2018
To LKK_req MV.tif	Letters and Correspondence	Internal	LOH Cynthia	July 16, 2018
RE- SURVEY PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 16, 2018
SURVEY PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 16, 2018
SURVEY PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 16, 2018
Mandate approved COR $7000.tif	Letters and Correspondence	Investigator / Adjustor	LOH Cynthia	July 16, 2018
FOR MANDATE.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 25, 2018
FOR MANDATE.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 25, 2018
LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 24, 2018
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	May 24, 2018
GA070558-Policy Schedule.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	HO Winnie	March 22, 2018
GA070558-Certificate of Insurance.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	HO Winnie	March 22, 2018