ASS. REC. BY: Silvelon Kenneth Meriman | REF: CO/MSIG18005383/Kvb | Special Instruction:

ASSIGNMENT (Office)

From (Person): Fievel FOO of MSIG Date/Time: 20032018 4.44pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLE 1449B Insured: YP 3589T

at Workshop m/s: Massive Trading Tel:

of: Blk 5038 Ang Ind Park 2 # 01-4105

Policy No: 2898 03113 MKC Claim No:

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 20032018

CA / REV / REP. / REV 24 HRS / WP

Date/Time: 21032018 10.13am Person Contacted: Anthony H.O. for Endorsement: Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLE 1449B - X
	YP 3589T - X
22/3/18	Send preli revised by meriman
3/4/18	C/Ln @ 930a Confirm Rec'd 12,700.64 3589

ASS. REC. BY: Kenneth | REF: MSG/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Mossine

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 08 days Res.: Yes or No

Lum Sum: 22 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLE1418B Yr Regn: 07, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Honda Vezel c.c 1496

Colour M. Silver A/C: Insured / Std / NI / NA

Sp.Reading 30708 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU1 · 1115997

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modl : Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front		Rear	
R/Bal.	6 mm	R/Bal.	7 mm
L/Bal.	6 mm	L/Bal.	7 mm
D.O.A.	20/3/18	D.O.I.	21/3/18

Survey held at _____

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chasis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
13	File pass to Catherine
	Kenneth, pls check parts prior

RECEIVED 04 APR 2018

23/3

Date/Time, File Pass to?

1) _____

Date/Time, File Return to?

2) 4/4 - typist

☐ : Prell. Report

☐ : Final Report

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ Tech Invs ($ _____)

☐ Weekend ($ _____)

Report Format : Mennen

Lump Sum / I.B.I: ($ 9300/-)

Survey Fee: 300

Transportation: $ + RS SI

Photos

Others

TOTAL

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Ref : CS/MSG18005282/Kvb

Date : 21-03-2018

Code : MSG

1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	YP 3589T	Veh. Inspected	SLE 1419B
	Policy No.	28980343MKC	Coverage ($)	0.00
	Claim No.		Excess ($)	0.00
	Assign From	MERIMEN (FIEVEL FOO)	Assign Date	20/03/2018

2.	Vehicle Particulars & Condition			
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			

3.	Conditions of Tyres			
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

4.	Description of Damages

5.	General Information			
	Accident Date	20/03/2018	Inspection Date	21/03/2018
	Survey held at	BLK 5038 AMK IND PARK 2 #01-405		
	Repairer	MASSIVE TRADING & AUTO		

5a.	Remarks
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Mar 2018		20 Mar 2018 16:44 Assign				**New Assignment** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	**FAR OCEAN SEA PRODUCTS (PTE) LTD**, Co. Reg. No.: 197101137C		
Main Claimant:	**CHAN SEE TANG**, ID: S0069576I		
Vehicle Reg. No.:	**SLE1419B**	Date of Loss:	20/03/2018 11:00 - :59
Claim Type:	**TP**	Policy/Cover Note No.:	28980343MKC (Comprehensive) Coverage: 23/07/2017 - 20/07/2018
Vehicle Reg. No. (Insured):	**YP3589T**	Policy No. (Claimant):	
		Excess:	
Repairer:	**Massive Trading & Auto ()** Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2, 569541 Ang Mo Kio - Tel:		
Handling Insurer:	**MSIG Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: +65 6827 7888 ... [Handled by **Fievel Foo Wenyao** - 6643 1316]		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [**Imm.Advice** due 21/03/2018]		
Adj Asg. Remarks:	request Kenneth Kong for survey		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

21/3/2018 @ 10:53am
Anbery wh in

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Fievel Foo Wenyao	Date:	22 Mar 2018

Preliminary Advice

Insured Vehicle No	: YP3589T		
TP Vehicle No	: SLE1419B	Accident Date	: 20/03/2018
Make	: HONDA VEZEL	Assignment Date	: 20/03/2018
Date of Inspection	: 21/03/2018	Est. Duration of Repair	: 8.00
Inspection At	: MASSIVE TRADING & AUTO BLK 5038 #01-405, ANG MO KIO INDUSTRIAL PK 2 SINGAPORE 569541		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S$	22,000.64	
Revised Amount	:S$	10,440.72	
Check Items (Estimated)	:S$	3,872.88	
Total	:S$	14,313.60	
Lump Sum Repair	:S$		

Total Loss Consideration

New for Old Value	:S$	
Pre-Accident Value	:S$	
COE / PARF Rebate	:S$	
Salvage Value	:S$	
Margin for Repair	:S$	

Remarks

( ) The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/03/2018 14:12
Date Of Accident	20/03/2018 11:50
Exact Location Of Accident	AMK AVE 6 SLIP RD TO AMK AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE1419B
Insured/Policyholder	
Name Of Registered Owner	CHAN SEE TANG
NRIC No	S0069576I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97316010
Alternative Phone No	OTHERS-97316010
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5082026403-01
Cover Note Number	
Driver	
Name of Driver	CHAN SEE TANG
NRIC No	S0069576I
Date Of Birth	29/09/1949
Occupation	INDOOR
Date Of Driving Pass	01/08/1974
Driving Experience	43 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97316010
Fax Number	

Address	BLK 586 AMK AVE 3 #11-3063
Postcode	560586
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN - CIRCUMSTANCES OF THE ACCIDENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP3589T
Vehicle Make/Model/Colour	ISUZU LORRY
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SU YANBING
NRIC/Passport Number	G2731847P
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

   I understand, acknowledge, agree and consent that:

   (a) My insurer, my workshop and the General Insurance Association of Singapore ("**GIA**") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

   (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

   (ii) investigating the accident and/or my claims;

   (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

   (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

   (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**")

   (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

   (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

   (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

   (e) the information so collected under (d) above may be shared / disclosed:

   (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or

   (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 20/3/2018 @ about 1150hrs, I was travelling along Ang Mo Kio Ave 6. At the slip rd to Ang Mo Kio Ave 1, I stopped at the dotted white line waiting for the main rd traffic to clear. While waiting, suddenly I felt an very strong impact from the rear of my vehicle. I got out of my vehicle and realised that veh B (YP3589T) had collided into my vehicle rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Massive Trading & Auto

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/P 91082728
Fax : 64816131

Not Authorise
C/Sup @ 9150/-
Resume After Paint
8 days

Chan See Tang
Blk 586 Ang Mo Kio Ave 3
#11=3063
Singapore 560586

Vehicle No : SLE 1419 B
Make/Model : Honda Vezel 1.5 X A
Year : 2017

Qty	Description	Unit Price	Amount
Estimate Cost Of Repair			
1 pc	Rear tail-gate assy 1100-90	Rp	$1,650.70 — 1209
1 pc	Rear tail-gate glass 1176	Shatterex	$1,386.10 —
2 pcs	Rear tail-gate side garnish	DIS/Un $107.10	$214.20 —
1 pc	Rear tail-gate glass centre garnish	Bu	$155.60 —
1 pc	Rear tail-gate glass moulding	Re	$105.20 —
1 pc	Rear tail-gate top spoiler	Sm	$376.10 X
1 pc	Rear third brake light	Un	$205.10 2
1 pc	Rear tail-gate outer garnish	Re	$385.60 —
2 pcs	Rear tail-gate damper	$85.10 Sm	$170.20 X
1 pc	Rear wiper motor	Sm	$425.10 2
1 pc	Rear wiper arm 108.00	Rd	$155.60 2
1 pc	Rear tail-gate emblem " H "	Re	$45.10 —
1 pc	Rear tail-gate emblem : Vezel "	Re	$50.20 —
1 pc	Rear tail-gate outer garnish repeat	Replace	$385.60 X
1 pc	Rear tail-gate inner lock	Rd	$285.60 —
1 pc	Rear tail-gate inner trim board 225.00	Bu	$455.90 2
2 pcs	Rear tail-gate lamp componegt 240.30	CM Rd/Gn $425.30	$850.60 —
2 pcs	Rear no plate lamp	Sm $65.10	$130.20 X
2 pcs	Rear tail-lamp assy 552.30	Un $855.90	$1,711.80 —
1 pc	Rear boor rubber	Rd/Dk $225.80	—
1 pc	Rear end panel	Rp	$455.10 —
1 pc	Rear end panel inner garnish	Re	$185.90 —
1 pc	Rear bumper 863.70	Rp	$955.60 —
2 pcs	Rear side bumper @ 301.60	Bu/CM $335.60	$671.20 2
2 pcs	Rear bumper side retainer	$38.20 Dk	$76.40 —
2 pcs	Rear bumper reflector	$137.10 Sm	$274.20 X
1 pc	Rear bumper lower garnish	CM	$175.20 2
1 pc	Rear radio antenna sensor	CM	$175.60 2
1 pc	Rear n/s fender	R	$1,185.90 X
2 pcs	Rear fender inner trim	MS Mgcm $425.10	$850.20 2
		balance c/f	$14,375.60

SLE 1419 B

		balance b/f	$14,375.60
2 pcs	Rear fender arch protector	$175.20	$350.40
2 pcs	Rear fender inner shield	$105.60	$211.20
1 pc	Rear spare tyre panel		$1,255.80
1 pc	Rear spare tyre tool sponge		$275.60
1 pc	Rear spare tyre top cover board		$385.60
1 pc	Rear exhaust silencer 785.36		$975.10
1 pc	Rear axle assy		$1,490.70
2 pcs	Rear shock absorber	$385.10	$770.20
2 pcs	Rear hub assy	$305.30	$610.60
			$20,700.80
		Less 20 %	$4,140.16
			$16,560.64

S Nett

1 pc	Rear tail-gate glass sealant		$55.00
1 pc	Rear reverse camera		$280.00
1 pc	Rear reverse sensor		$200.00
20 pcs	Rear bumper clip	$3.00	$60.00
1 pc	Rear no plate		$40.00
1 pc	Rear CCTV		$450.00
			$635.00

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.	$1,800.00
To putty and spray paint	$1,600.00
Check & reconnect wiring.	$45.00
To respray anti-rust proofing treatment	$180.00
Remove/refit rear windscreen to facilitate repair	$100.00
Remove/refit rear tail-gate mechanism to new door.	$150.00
Remove/renew rear exhaust silencer.	$120.00
Remove/refit rear boot upholstery to facilitate repair.	$100.00
Remove/renew rear axle, hub and shock abosrber.	$450.00
Check and realign wheel alignment.	$80.00
Diagnostic check on rear ABS and to reset same.	$180.00
Total	$22,000.64

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Mar 2018		20 Mar 2018 16:44 Edit Adj Rpt	**S$9,300.00** Edit Estimates	**S$9,300.00** View Rpt		**Pending for Survey Report** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS			**[Created by insurer]**
Insured:	**FAR OCEAN SEA PRODUCTS (PTE) LTD**, Co. Reg. No.: 197101137C		
Main Claimant:	**CHAN SEE TANG**, ID: S0069576I		
Vehicle Reg. No.:	**SLE1419B**	Date of Loss:	20/03/2018 11:00 - :59 [**20** Months and **9** Days From LTA Reg Date (Man Yr)]
Claim Type:	**TP** / 552974	Policy/Cover Note No.:	A2B980343MKC (Comprehensive) Coverage: 23/07/2017 - 20/07/2018
Vehicle Reg. No. (Insured):	**YP3589T**	Policy No. (Claimant):	
		Excess:	
Repairer:	**Massive Trading & Auto ()** Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2, 569541 Ang Mo Kio - Tel:		
Handling Insurer:	**MSIG Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: +65 6827 7888 ... [Handled by **Fievel Foo Wenyao** - 6643 1316]		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **KENNETH KONG**] ... [**Final Rpt** due 19/04/2018]		
Adj Asg. Remarks:	request Kenneth Kong for survey		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

Claim Documents

***SLE1419B (552974)**
[YP3589T]
TP
CHAN SEE TANG
Mar 20 2018 11:00AM
[FAR OCEAN SEA PRODUCTS (PTE) LTD]
Massive Trading & Auto

Upload Documents | Upload Photos | Compose New Letter

View: View in Browser

Assessment Reports			1 per page		☑
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	21/03/18 15:23	**Accident Statement** From:SC - Reg. No: YP3589T, Claimant: FAR OCEAN SEA PRODUCTS (PTE) LTD		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/03/18 16:26	**Adjuster Immediate Advice**		Load HTM	

Photos/Images			3 per page		☑
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/03/18 16:27	General View		Load JPG	☑
2	22/03/18 16:27	General View		Load JPG	☑
3	22/03/18 16:27	General View		Load JPG	☑
4	22/03/18 16:27	General View		Load JPG	☑
5	22/03/18 16:27	General View		Load JPG	☑
6	22/03/18 16:27	General View		Load JPG	☑
7	22/03/18 16:27	General View		Load JPG	☑
8	22/03/18 16:27	General View		Load JPG	☑
9	22/03/18 16:27	General View		Load JPG	☑
10	22/03/18 16:27	General View		Load JPG	☑
11	22/03/18 16:27	General View		Load JPG	☑
12	22/03/18 16:27	General View		Load JPG	☑
13	22/03/18 16:27	General View		Load JPG	☑
14	22/03/18 16:27	General View		Load JPG	☑
15	22/03/18 16:27	General View		Load JPG	☑
16	22/03/18 16:27	General View		Load JPG	☑
17	22/03/18 16:27	General View		Load JPG	☑
18	22/03/18 16:27	General View		Load JPG	☑
19	22/03/18 16:27	General View		Load JPG	☑
20	22/03/18 16:27	General View		Load JPG	☑
21	22/03/18 16:27	General View		Load JPG	☑
22	22/03/18 16:27	General View		Load JPG	☑
23	22/03/18 16:27	General View		Load JPG	☑
24	22/03/18 16:27	General View		Load JPG	☑
25	22/03/18 16:27	General View		Load JPG	☑
26	22/03/18 16:27	General View		Load JPG	☑
27	22/03/18 16:27	General View		Load JPG	☑
28	22/03/18 16:27	General View		Load JPG	☑
29	22/03/18 16:27	General View		Load JPG	☑
30	22/03/18 16:27	General View		Load JPG	☑
31	22/03/18 16:27	General View		Load JPG	☑
32	22/03/18 16:27	General View		Load JPG	

Assessment Reports			1 per page		☑
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
					☑
33	22/03/18 16:27	General View		Load JPG	☑
34	22/03/18 16:27	General View		Load JPG	☑
35	22/03/18 16:27	General View		Load JPG	☑
36	22/03/18 16:27	General View		Load JPG	☑
37	22/03/18 16:27	General View		Load JPG	☑
38	04/04/18 08:31	Reinspection Photo		Load JPG	☑
39	04/04/18 08:31	Reinspection Photo		Load JPG	☑
40	04/04/18 08:31	Reinspection Photo		Load JPG	☑
41	04/04/18 08:31	Reinspection Photo		Load JPG	☑
42	04/04/18 08:31	Reinspection Photo		Load JPG	☑
43	04/04/18 08:31	Reinspection Photo		Load JPG	☑
44	04/04/18 08:31	Reinspection Photo		Load JPG	☑
45	04/04/18 08:31	Reinspection Photo		Load JPG	☑
46	04/04/18 08:31	Reinspection Photo		Load JPG	☑
47	04/04/18 08:31	Reinspection Photo		Load JPG	☑
48	04/04/18 08:31	Reinspection Photo		Load JPG	☑
49	04/04/18 08:31	Reinspection Photo		Load JPG	☑
50	04/04/18 08:31	Reinspection Photo		Load JPG	☑
51	04/04/18 08:31	Reinspection Photo		Load JPG	☑

Documentation			1 per page		☑
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	20/03/18 16:48	PRI from Teo Keng Siang LLC		Load PDF	
2	20/03/18 16:48	SLE1419B Report		Load PDF	
3	20/03/18 16:48	Survey Agree on SJE		Load PDF	
4	21/03/18 15:23	SLE1419B E-FILE REPORT From:SC - Reg. No: YP3589T, Claimant: FAR OCEAN SEA PRODUCTS (PTE) LTD		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18005282/KVBQ2
Date: 05/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28980343MKC		
Claimant Vehicle No :	SLE1419B	**Insured Vehicle No :**	YP3589T		
Date of Loss:	20/03/2018	Nature of Claim:	TP	Claim No:	552974

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	**SLE1419B**		
Make & Model:	HONDA VEZEL, 1.5 1.5X CVT (A)	Engine No:	L15B4036003
Reg. Date:	11/07/2016 (Man. Year: 2016)	Chassis No:	RU11115997
Colour:	Metallic Silver	Odometer:	30708 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S$):	**Market Value/New Car Price**		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,645.64	9,121.28	8,524.36	48.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,805.00	2,480.00	2,325.00	48.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S$)	**22,450.64**	**11,601.28**	**10,849.36**	**48.33**
Approved Total (Overridden) (S$)		**9,300.00**		
Nett Amount (S$)	**22,450.64**	**9,300.00**	**13,150.64**	**58.58**

INSPECTION

Date of Assignment:	20/03/2018		
Date Inspected:	21/03/2018	Inspected At:	Massive Trading & Auto Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2 Singapore 569541
Estimated Period of Repair:	8.0 days		

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Apr 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE1419B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL-GATE ASSY	Bent	1,650.70 FL	*1,100.90 FL
2	1		*REAR TAIL-GATE GLASS	Shattered	1,386.10 FL	*1,176.00 FL
3	2		*REAR TAIL-GATE SIDE GARNISH	Distorted / Cut	214.20 FL	*214.20 FL
4	1		*REAR TAIL-GATE GLASS CENTRE GARNISH	Buckled	155.60 FL	*155.60 FL
5	1		*REAR TAIL-GATE GLASS MOULDING	Necessary	105.20 FL	*105.20 FL
6	1		*REAR TAIL-GATE TOP SPOILER	Serviceable	376.10 FL	*- FL
7	1		*REAR THIRD BRAKE LIGHT	Cut	205.10 FL	*205.10 FL
8	1		*REAR TAIL-GATE OUTER GARNISH	Dented	385.60 FL	*385.60 FL
9	2		*REAR TAIL-GATE DAMPER	Serviceable	170.20 FL	*- FL
10	1		*REAR WIPER MOTOR	Jammed	425.10 FL	*425.10 FL
11	1		*REAR WIPER ARM	Dented	155.60 FL	*108.00 FL
12	1		*REAR TAIL-GATE EMBLEM H	Necessary	45.10 FL	*45.10 FL
13	1		*REAR TAIL-GATE EMBLEM VEZEL	Necessary	50.20 FL	*50.20 FL
14	1		*REAR TAIL-GATE OUTER GARNISH	Repeated	385.60 FL	*- FL
15	1		*REAR TAIL-GATE INNER LOCK	Dented	285.60 FL	*285.60 FL
16	1		*REAR TAIL-GATE INNER TRIM BOARD	Buckled	455.90 FL	*225.00 FL
17	2		*REAR TAIL-GATE LAMP COMPONENT	Cracked / Cut	850.60 FL	*480.60 FL
18	2		*REAR NO PLATE LAMP	Serviceable	130.20 FL	*- FL
19	2		*REAR TAIL-LAMP ASSY	Cut	1,711.80 FL	*1,104.60 FL
20	1		*REAR DOOR RUBBER	Dented / Distorted	225.80 FL	*225.80 FL
21	1		*REAR END PANEL	Bent	455.10 FL	*455.10 FL
22	1		*REAR END PANEL INNER GARNISH	Dented	185.90 FL	*185.90 FL
23	1		*REAR BUMPER	Bent	955.60 FL	*863.70 FL
24	2		*REAR SIDE BUMPER	Buckled / Cracked	671.20 FL	*603.20 FL
25	2		*REAR BUMPER SIDE RETAINER	Distorted	76.40 FL	*76.40 FL
26	2		*REAR BUMPER REFLECTOR	Serviceable	274.20 FL	*- FL
27	1		*REAR BUMPER LOWER GARNISH	Cracked	175.20 FL	*175.20 FL
28	1		*REAR RADIO ANTENNA SENSOR	Cracked	175.60 FL	*175.60 FL
29	1		*REAR N/S FENDER	Repair	1,185.90 FL	*- FL
30	1		*REAR FENDER INNER TRIM	N/S Mtg Cracked	850.20 FL	*425.10 FL
31	2		*REAR FENDER ARCH PROTECTOR	Buckled	350.40 FL	*350.40 FL
32	2		*REAR FENDER INNER SHIELD	Serviceable	211.20 FL	*- FL
33	1		*REAR SPARE TYRE PANEL	Repair	1,255.80 FL	*- FL
34	1		*REAR SPARE TYRE TOOL SPONGE	Cracked	275.60 FL	*275.60 FL
35	1		*REAR SPARE TYRE TOP COVER BOARD	Serviceable	385.60 FL	*- FL
36	1		*REAR EXHAUST SILENCER	Bent	975.10 FL	*785.30 FL
37	1		*REAR AXLE ASSY	Serviceable	1,490.70 FL	*- FL
38	2		*REAR SHOCK ABSORBER	Serviceable	770.20 FL	*- FL
39	2		*REAR HUB ASSY	Serviceable	610.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR TAIL-GATE GLASS SEALANT	Necessary	55.00 FS	*40.00 FS
41	1		*REAR REVERSE CAMERA	Shorted	280.00 FS	*250.00 FS
42	1		*REAR REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
43	20		*REAR BUMPER CLIP	Necessary	60.00 FS	*60.00 FS
44	1		*REAR NO PLATE	Dented	40.00 FS	*40.00 FS
45	1		*REAR CCTV	Serviceable	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S$)	**21,785.80**	**11,254.10**
- List Item Discount on L Items 20.00/20.00% (S$)	4,140.16	2,132.82
Total Parts (S$)	**17,645.64**	**9,121.28**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING ,WELDING & CUTTING	New	1,800.00	1,000.00
2	TO PUTTY AND SPRAY PAINT	New	1,600.00	1,080.00
3	CHECK & RECONNECT WIRING	New	45.00	20.00
4	TO RESPRAY ANTI-RUST PROOFING TREATMENT	New	180.00	60.00
5	REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIR	New	100.00	100.00
6	REMOVE/REFIT REAR TAIL-GATE MECHANISM TO NEW DOOR	New	150.00	60.00
7	REMOVE/RENEW REAR EXHAUST SILENCER	New	120.00	60.00
8	REMOVE/REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	100.00	100.00
9	REMOVE/RENEW REAR AXLE ,HUB AND SHOCK ABSORBER	New	450.00	0.00
10	CHECK AND REALIGN WHEEL ALIGNMENT	New	80.00	0.00
11	DIAGNOSTIC CHECK ON REAR ABS AND TO RESET SAME	New	180.00	0.00
		Gross Labour Cost (S$)	**4,805.00**	**2,480.00**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >