English (default) LHK AUTO CONSULTANTS PTE LTD (TP)

SERVICE REQUESTS MESSAGES CLAIMS

				PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
				REAR TAILLAMP INNER PANEL LH			Bent	105.4		20		84.32	Reviewing	
	12	1		REAR BUMPER			Bent	663.7		20		530.96	Reviewing	
	13	1		REAR BUMPER SIDE RETAINER LH + RH (N/S)			Damaged	27.5		20		22	Reviewing	
	14	10		REAR BUMPER CLIP			Necessary	3.9		20		31.2	Reviewing	
	15	1		REAR END PANEL			Bent	423.9		20		339.12	Reviewing	
	16	1		REAR END PANEL INNER TOP GARNISH			Damaged	96.6		20		77.28	Reviewing	
	17	4		REAR END PANEL INNER TOP GARNISH CLIP			Necessary	5.9		20		18.88	Reviewing	
	18	1		REAR WELL PANEL INNER TOP TOOL SPONGE			Deformed	180.5		20		144.4	Reviewing	
	19	1		REAR WELL PANEL INNER TOP UPHOLSTERY BOARD			Deformed	286.6		20		229.28	Reviewing	

Labour

Add Approve Deny Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION.	700	0	0	Reviewing		

English (default) ▾ LHK AUTO CONSULTANTS PTE LTD (TP) ▾

SERVICE REQUESTS MESSAGES CLAIMS

ASSESSMENT INFORMATION

0

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Issue Date		mm/dd/yyyy
License Expiration Date		mm/dd/yyyy
Address	515 YIO CHU KANG ROAD, #02-44, 787083, Singapore	
Address type	Personal Correspondence	
Gender	Male	
Marital status	Unknown	
Identification #	S7182419E	

English (default) LKK AUTO CONSULTANTS PTE LTD (TP)

SERVICE REQUESTS MESSAGES CLAIMS

	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	November 2, 2018
LKK Reinspection Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	November 2, 2018
After Repair Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	November 2, 2018
LKK Inspection Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	November 2, 2018
RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	October 1, 2018
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	October 1, 2018
TP ESTIMATE- MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	March 22, 2018
Preliminary Advice.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	March 22, 2018
EMAIL FROM WORKSHOP.msg	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	March 21, 2018
GIA REPORT OF SLR5277Z (TP).PDF	Reports & Statement	GIA Report	KADRI Mateen	March 21, 2018
GIA REPORT OF SKU717A (INSD).PDF	Reports & Statement	GIA Report	KADRI Mateen	March 21, 2018