COMFORTDELGRO ENGINEERING PTE LTD

QBE-LKK

REPAIR ESTIMATE*

VEHICLE NO : SHC 1745S **DATE 21/3/2018 10:51**

FZ

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover			$ 538.80	
	Front Bumper Bracket Top (LH)			$ 22.40	
	Front Bumper Protector (LH)			$ 29.20	
	Headlamp Support Panel Assy			$ 1,023.00	?
	Headlamp (LH)			$ 797.90	
	Front Fender (LH)			$ 593.00	
	Front Fender Shield (LH)			$ 86.00	
	Front Fender Retainer			$ 9.20	
	SUB TOTAL			**$ 3,099.50**	
	LESS 20%			$ 619.90	
	DISCOUNTED TOTAL			**$ 2,479.60**	
	Front Fender Advertisement Logo (LH)			$ 100.00	Nett
				$ 100.00	
	Labour Charge				
	Panel Beating		support panel +200?	~~$ 750.00~~	400
	Spray Painting Charge			~~$ 400.00~~	360
	Wiring Charge			~~$ 50.00~~	30
	Tuff Kote			~~$ 50.00~~	30
	Remove/Refix Aircon & Refill Gas			~~$ 150.00~~	80?
	TOTAL LABOUR			**$ 1,400.00**	
	ESTIMATE TOTAL			**$ 3,979.60**	

Repair
Hyundai 900/100 C8
4 days
L/S
22/03/18 @ 0950
Reg after repair

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.