LKK Auto Consultants Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: LSP/RSS/8172/14/nr

Date: 03rd April 2018

Our Ref: CS1/LAW18005522/Uvbs2

M/s Lee Shergill LLP
111 North Bridge Road
#07-07 Peninsula Plaza
Singapore 179098

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKD 1518R INSURED VEHICLE: JKP 7719 ACCIDENT DATE: 16/05/2014

We thank you for your instruction on 19/03/2018.

We acknowledge receipt of the following documents:-

a) Survey report by RT Appraisal Pte Ltd with colour photographs.
b) Final Repair Bill of SKD 1518R from M/s Tan Lim Motor Pte Ltd.
c) Singapore Accident Statement of Vehicles SKD 1518R.
d) Colour damaged vehicle photographs of SKD 1518R.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKD 1518R
Make & Model	: BMW 730I
Year of Registration	: 2005
Chassis Number	: WBAHL220X0DD51204
Engine Capacity	: 2996 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.