REF: NS/INC1800 5693 /Sthez

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SGN 2724A

Policy No. 5014685055G-01 14.11.17 - 13.11.18

Claims No. MT/0907576-002

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No. SHB 5490E. Yr Regn: 12/10/2017.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toyota Prius 4. cc 1798

Colour Mercury. A/C: Insured / Std / NI / NA

Sp.Reading 78503 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTDKB3[illegible]7035-7289[illegible]

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : NM / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	7 mm	R/Bal.	7 mm
L/Bal.	7 mm	L/Bal.	7 mm
D.O.A.	25/3/18.	D.O.I.	26/3/18.

Survey held at SMART.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHB 5490E - [illegible]
	SGN 2724A - [illegible]
	TAX/03/18/2121 Lkk.
	NTUC.
	Part by Part $3428.77 (Red. 4390.33:567.)
	SGN 2724A

RECEIVED [illegible] APR 2018

Date/Time File Pass to? : Preli. Report

2nd Typist : Final Report

Date/Time File Return to?

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: Site Insp ($) Survey Fee: 160

Interview ($) Transportation ($ + $)

Tech. Inv's ($) Photos 35

Weekend ($) Others

Report Format : TP

Lump Sum / I.B.I: ($ 3428.77) TOTAL 195

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6841 0055 FAX: 6841 6315
Reg. No: 52983356E GST Reg. No. 20-0405911-H

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18005693/Stb

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556

Date: 27-03-2018

Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

	Insured Veh.	SGN 2724A	Veh. Inspected	SHB 5490E
	Policy No.	5046850556-07	Coverage ($)	0.00
	Claim No.		Excess ($)	0.00
	Assign From		Assign Date	26/03/2018

2. Vehicle Particulars & Condition

	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			

3. Conditions of Tyres

		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

4. Description of Damages

5. General Information

	Accident Date	25/03/2018	Inspection Date	26/03/2018
	Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

eBaoTech GeneralClaim

Hello, NAC_PAYA_UBI_800601

Change Language | Change Password | Log Out

My Desktop

Notice of Loss

Policy Query

Policy No.

Vehicle No.(For Motor) SGN2724A

Date of Accident 25/03/2018 19:01

Search

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
◉	5046850556-07	LIM SEE HOR	S7417124I	GPC	Third Party, Fire & Theft	SGN2724A	SGN2724A	14/11/2017	13/11/2018

Continue

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
1	**MT/0991340-002**	COMFORT TRANSPORTATION PTE LTD	SH 7013A	SJL 3277S
2	**MT/0990420-002**	COMFORT TRANSPORTATION PTE LTD	SHC 1833X	GBG 6935C
3	**MT/0991001-002**	COMFORT TRANSPORTATION PTE LTD	SHB 4181D	SJF 4165G
4	**MT/0987576-002**	SMRT TAXIS	SHB 5490E	SGN 2724A
5	**MT/0988974-002**	SMRT TAXIS	SHF 474P	SKP 1761R
6	**MT/0988606-002**	SMRT TAXIS	SHF 287M	SHD 1850R
7	**MT/0988375-002**	SMRT TAXIS	SHB 5737U	SKZ 9804X
8	**MT/0991050-002**	COMFORT TRANSPORTATION PTE LTD	SHD 6647D	SLM 4176P
9	**MT/0991603-001**	COMFORT TRANSPORTATION PTE LTD	SH 9594B	SJF 8421R
10	**MT/0989297-002**	SMRT TAXIS	SHB 5445L	GZ 8719M
11	**MT/0989010-002**	SMRT TAXIS	SHB 668T	SLV 3014H
12	**MT/0988555-002**	SMRT TAXIS	SHB 5515T	SLS 2028R
13	**MT/0981124-002**	SMRT BUSES	SMB 8039Y	SJC 8146B
14	**MT/0991610-001**	COMFORT TRANSPORTATION PTE LTD	SHC 8728X	GBG 2031L
15	**MT/0991074-002**	COMFORT TRANSPORTATION PTE LTD	SHC 2948S	GZ 1977E
16	**MT/0990979-002**	COMFORT TRANSPORTATION PTE LTD	SHD 6658Y	FBK 791T
17	**MT/0990696-002**	COMFORT TRANSPORTATION PTE LTD	SHD 4138U	PC 2948Y
18	**MT/0990960-002**	COMFORT TRANSPORTATION PTE LTD	SHD 4928G	YP 6440T

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	5369K

Vehicle Details

Vehicle No.:	SHB5490E
Vehicle to be Exported:	No
Intended De-registration Date:	27 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS097862
Chassis No.:	JTDKB3FU703572891
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	$29,007.00
Original Registration Date:	12 Oct 2017
First Registration Date:	12 Oct 2017
Transfer Count:	0
Actual ARF Paid:	$5,000.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Oct 2025
PARF Rebate Amount:	$3,750.00

Intended COE Rebate Details

COE Expiry Date:	11 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	$34,052.00
COE Rebate Amount:	$32,085.00
Total Rebate Amount:	**$35,835.00**

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 27 Mar 2018

OK

MSR118040208 / SMRT Automotive Services Pte Ltd - Woodlands
ENTRY DATE & TIME: 26/03/2018 09:44
SUBMITTED BY: B. Thaiyal Nayagi

Your NCD will be affected due to late reporting
Actual e-Filling Submission Date & Time: 27/03/2018 08:44

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/03/2018 09:44
Date Of Accident	25/03/2018 01:05
Exact Location Of Accident	WOODLANDS ST 41 /WOODLANDS AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5490E

Insured/Policyholder

Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

Driver

Name of Driver	TOH SONG YONG
NRIC No	S0182127Z
Date Of Birth	09/12/1951
Occupation	OUTDOOR
Date Of Driving Pass	18/07/1969
Driving Experience	48 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	10-402
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CHUA YEOW CHERN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes,Please state which Police Station	
Police Station Name	WOODLANDS NPC
Police Station Address	**ROAD**: 3 WOODLANDS DRIVE 63 , **POSTCODE:** 737890 , **COUNTRY**: SINGAPORE
Police Station Contact	**TEL NO**: - **FAX NO**:
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20180325/2020

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	UNKNOWN
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1



26-03-18

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time: 26-03-18	Reporting Centre Personnel's Signature Name: NRIC/FIN No.: 26/3/2018

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

   I understand, acknowledge, agree and consent that:

   (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

   (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

   (ii) investigating the accident and/or my claims;

   (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

   (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

   (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")

   (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

   (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

   (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

   (e) the information so collected under (d) above may be shared / disclosed:

   (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

   (ii) for complying with requirements under any regulations, laws or court orders.

SMART TAXIS PTE LTD

26-03-18

26/3/2018

Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

SINGAPORE POLICE FORCE

T/20180325/2020

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

Report No. T/20180325/2020

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:	Vide Report No.:	Station Diary No.:
25/03/2018 03:48	J/20180325/0020	26

Name of Informant: TOH SONG YONG			Address: APT BLK 650 WOODLANDS RING ROAD #10-402 SINGAPORE 730650	
ID Type / ID No.: NRIC NO / S0182127Z			Contact No.: Home/Office: Mobile: 97911846	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 66	Date of Birth: 09/12/1951	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3	Date of Expiry:

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 25/03/2018 01:05	Type of Location: T-Junction

Location:
Along Road 1 Traveling Toward Road 2
WOODLANDS STREET 41
WOODLANDS AVENUE 1
At the T junction of woodlands ave1 and woodlands street 41

Weather:	Road Surface:	Road Speed Limit:
Clear	Dry	
Traffic Flow: Dual Carriage Way	Traffic Control: Traffic Light - Working	Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear		Anyone conveyed by ambulance: No

SGN2724A	Car				No Damage	0
SHB5490E	Car				Slightly Damaged	1

Any Pedestrian Involved: No

No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

SINGAPORE POLICE FORCE

T/20180325/2020

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

Report No. T/20180325/2020

CONTINUATION OF REPORT

Name	TOH SONG YONG	ID No.	S0182127Z
Related Vehicle	SHB5490E (Car)	Contact No.	97911846
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL

Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 25/03/2018 at about 0105hrs I was driving my taxi with plate number SHB5490E along woodlands avenue 1 toward avenue 2 on lane 2. I stop my vehicle at the T junction as the traffic light indicate red. As soon as it turns green, I move off slowly as my passenger wants to alight a few meters after the junction. Subsequently, a car with plate number SGN2724A collided to the rear side of my vehicle. We both stopped and went out to make a check. My passenger namely Chua Yeow Chem, hp: 90667250, confronted the driver as he smell of alcohol. The driver admits that he drank 2 cups. As my passenger called the police, he quickly went in his vehicle and drive off quickly.

Traffic police, T130152 was at scene.
No ambulance and no one was injured.

My vehicle sustained from dents and scratches on the rear right side.

I have in build camera in my taxi which I have handed it over to the TP at scene.

SINGAPORE POLICE FORCE

T/20180325/2020

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

Report No. T/20180325/2020

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: J / MUHAMMAD SUFIAN BIN MUHAMMAD HOZIR BONAWI Signature :	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 25/03/2018 03:48
Officer In Charge Of Case: TP / HRT / SI TAN LEE HWANG DAWN Contact No.: 65476215	Classification Of Case:

Authentication Stamp
NP168

Accident Photo



Accident Photo

Accident Photo



SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No	:	SHB5490E
Ref. No	:	TAX/03/18/2121
Reg. Date	:	12/10/2017
Vehicle Type	:	TAXI
Make	:	TOYOTA PRIUS
Model	:	PRIUS4
Name of Driver	:	TOH SONG YONG
Type of Accident	:	HEAD TO REAR
Date / Time of Accident	:	25/03/2018 01:05:00 AM
Accident Reported Date / Time	:	26/03/2018 12:00:00 AM
Surveyor is Required?	:	Yes
Survey by	:	
Vehicle is Towed Back?	:	No
Towed Back Date/Time	:	
Replacement Vehicle issued?	:	No
Accident Repair Job Card No	:	000024095220
Special Instruction to ARC,if any	:	

SGN2724A - NTUC IDAC

Prepared Date : 26/03/2018 10:09:57 AM



Sebastian.
26/3/18.
- Part by part repair.
- Question Mark Item Photo
- Photo Before Paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU703572891 Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

		Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labout Charges	:	845.00	0.00
Total Spray Painting Charges	:	1,116.00	0.00
Total Material Charges	:	4,209.62	4,209.62
Other Charges	:	360.00	0.00
TOTAL	**:**	**6,530.62**	**0.00**
Lum Sum Total	**:**	**0.00**	**0.00**
No. of Repair Days	:	6.00	~~0.00~~ 3days
Prepared / Adjusted By	:		
Arc / Surveyor Sing Off Date	:	26/03/2018 02:29:10 PM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 26/03/2018 02:29:10 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :

Quotation Date : Invoice Date :

Invoice Amount : Prepared Date :

ection D - Details of Repair Estimates

art 1 - Labour Works

ob Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O REPAIR RH REAR PORTION	845.00	~~0.00~~ 460
otal Labour	**845.00**	**0.00**

art 2 - Spray Painting & Panel Beating Related Works

ob Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O REPSRAY REAR BUMPER	378.00	~~0.00~~ 200
O RESPRAY BUMPER BEAM	180.00	0.00
O RESPRAY TAIL GATE	378.00	0.00
O RESPRAY TAILGATE OUTSIDE GARNISH	180.00	~~0.00~~ 100
otal Spray Painting & Panel Beating	**1,116.00**	**0.00**

art 3 - Other Costs - Accident and Accident Repair Related Expenses

ob Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
O TEST AND REFIX REVERSE SENSOR YSTEM	120.00	~~0.00~~ 30
O REPLACE SUNDRY PARTS	100.00	0.00 X
O WASH AND VACUUM	60.00	0.00 X
otal Other Costs	**360.00**	**0.00**

Part Number	Portion	Stock No	Part Name	Qty	List Price ($)	Discount (%)	Final Price ($)	ARC Recommend	Surveyor Approved	Photos Attached
52159479 3			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No
52462470 0			PAD, RR BUMPER, RH & LH , 1	2	3.80	25.00	5.70	Replace	Replace	No
52462470 0			PAD, RR BUMPER, RH & LH , 2	2	3.80	25.00	5.70	Replace	Replace	No
52462470 0			PAD, RR BUMPER, RH & LH , 3	2	3.80	25.00	5.70	Replace	Replace	No
52191470 0			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace	No
52575470 0			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.52	Replace	Replace	No
52565479 0			FILLER, RR BUMPER , RH	1	119.90	25.00	89.92	Replace	Replace	No
52591470 0			SEAL, RR BUMPER , RH	1	85.20	25.00	63.90	Replace	Replace	No
52161160 0			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace	No
51581470 0			LENS & BODY ASSY , RR BUMPER , RH	1	486.80	10.00	438.12	Replace	Replace	No
52453470 0			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace	No
52169470 0			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace	No
52461470 0			PAD, RR BUMPER, CTR	3	2.20	25.00	4.95	Replace	Replace	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No
52023470 0			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace	No
58398470 0			COVER, REAR FLOOR UNDER , RH	1	169.50	25.00	127.12	Replace	Replace	No
56259470 0			COVER, REAR FLOOR UNDER CENTER	1	222.60	25.00	166.95	Replace	Replace	No
57005474 0			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	25.00	697.20	Replace	Replace	No
53801471 0A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace	No
			STICKER SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No
55441470 0			NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No
55442471 0			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No
55403480 0			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace	No
51551472 1			LENS & BODY, REAR COMBINATION LAMP , RH	1	438.10	10.00	394.29	Replace	Replace	No
			TOTAL MATERIALS					**4,209.66**	**4,209.62**	
			TOTAL MATERIALS(Discounted)					**4,209.62**	**4,209.62**	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price ($)	Discount (%)	Final Price ($)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Part 4 - Spare Parts / Material Usage

SMRT Automotive Service Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

29-3-18/10:45
29-3-18/14:47
26-3-18/14:45

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No	:	SHB5490E
Ref. No	:	TAX/03/18/2121
Reg. Date	:	12/10/2017
Vehicle Type	:	TAXI
Make	:	TOYOTA PRIUS
Model	:	PRIUS4
Name of Driver	:	TOH SONG YONG
Type of Accident	:	HEAD TO REAR
Date / Time of Accident	:	25/03/2018 01:05:00 AM
Accident Reported Date / Time	:	26/03/2018 12:00:00 AM
Surveyor is Required?	:	Yes
Survey by	:	Sebastian
Vehicle is Towed Back?	:	No
Towed Back Date/Time	:	
Replacement Vehicle issued?	:	No
Accident Repair Job Card No	:	000024095220
Special Instruction to ARC,if any	:	



SGN2724A - NTUC IDAC P/P
BEFORE PAINT PHOTO ,FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK)
& Email :sebastianyeang @lkkauto.com HP:90036121

Prepared Date : 26/03/2018 10:09:57 AM

Recording Camera	☐	☑
Radio Antenna	☐	☑

1st witness _____ Date 26-3-18
2nd witness _____ Date _____

E 1/2 (1) F
KM 18502

Vehicle to Woga Date In: 26/3/18 Towing: _____
Time In: 1650 Driver: AHA
Woga Job No: 53/C210
Vehicle sent to SMRT Date In: 31/8/18 Towing: _____
Time In: 1025 Driver: _____
Received by (SMRT) : _____

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU703572891 Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

		Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labout Charges	:	845.00	600.00
Total Spray Painting Charges	:	1,296.00	600.00
Total Material Charges	:	4,209.64	2,198.97
Other Charges	:	360.00	30.00
TOTAL	:	**6,710.64** 7819.10	**3,428.97**
Lum Sum Total	:	**0.00**	**0.00**
No. of Repair Days	:	6.00	5.00
Prepared / Adjusted By	:		SEBASTIAN (LKK)
Arc / Surveyor Sing Off Date	:	26/03/2018 02:29:10 PM	26/03/2018 02:45:35 PM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 26/03/2018 02:29:10 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1804-0255 Invoice No :

Quotation Date : 11/4 Invoice Date :

Invoice Amount : Prepared Date :

2198.97 /
+ 600.00 /
+ 630.00 /
3428.97 /

Sebastian
23/4/18

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	845.00	600.00
Total Labour	**845.00**	**600.00**

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00
TO RESPRAY BUMPER BEAM	180.00	0.00
TO RESPRAY TAIL GATE	378.00	200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100.00
TO RESPRAY REAR PANEL	180.00	100.00
Total Spray Painting & Panel Beating	**1,296.00**	**600.00**

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	**360.00**	**30.00**

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price ($)	Discount (%)	Final Price ($)	ARC Recommend	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No
5246247030			PAD, RR BUMPER, RH & LH , 1	2	3.80	25.00	5.70	Replace	Check	No
5246247020			PAD, RR BUMPER, RH & LH , 2	2	3.80	25.00	5.70	Replace	Check	No
5246247010			PAD, RR BUMPER, RH & LH , 3	2	3.80	25.00	5.70	Replace	Check	No
5219147030			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Check	No
5257547040			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.53	Replace	Check	No
5256547900			FILLER, RR BUMPER , RH	1	119.90	25.00	89.93	Replace	Replace S	No
5259147050			SEAL, RR BUMPER , RH	1	85.20	25.00	63.90	Replace	Check	No
5216116010			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace	No
8158147010			LENS & BODY ASSY , RR BUMPER , RH	1	486.80	10.00	438.12	Replace	Check	No
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.73	Replace	Replace S	No
5216947020			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace	No
5246147010			PAD, RR BUMPER, CTR	3	2.20	25.00	4.95	Replace	Check	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace S	No
5202347030			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace S	No
5839847050			COVER, REAR FLOOR UNDER , RH	1	169.50	25.00	127.13	Replace	Check	No
6625947010			COVER, REAR FLOOR UNDER CENTER	1	222.60	25.00	166.95	Replace	Check	No
6700547440			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	25.00	697.20	Replace	Check	No
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace	No
			STICKER SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No
7544147090			NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No
7544247130			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No
7540348010			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace	No
8155147281			LENS & BODY, REAR COMBINATION LAMP , RH	1	438.10	10.00	394.29	Replace	Check	No
TOTAL MATERIALS									4,209.66	2,198.97
TOTAL MATERIALS(Discounted)									4,209.64	2,198.97

Added Spare Parts / Material Usage After Surveyor Signed off

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

Thatcham escribe

idac

NTUC INCOME INSURANCE CO-OPERATIVE LTD

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Ref: NS/INC18005693/Stbe2

Date: 27-04-2018

Code: INC4

1. Policy Particulars - THIRD PARTY CLAIM

	Insured Veh.	SGN 2724A	**Veh. Inspected**	SHB 5490E
	Policy No.	5046850556-07	**Coverage ($)**	0.00
	Claim No.	MT/0987576-002	**Excess ($)**	0.00
	Assign From		**Assign Date**	26/03/2018

2. Vehicle Particulars & Condition

	Make & Model	TOYOTA PRIUS 4	**c.c**	1798
	Engine No.	HIDDEN	**Year of Reg.**	2017
	Chassis No.	JTDKB3FU703572891	**Colour**	MAROON
	Odometer	78503	**Steering**	IN ORDER
	Brakes	IN ORDER	**Modification**	NIL
	General	FAIR		

3. Conditions of Tyres

		Size	**Make**	**Balance**
	R/H Front Tyre	195/65 R15	YOKOHAMA	7 mm
	L/H Front Tyre	195/65 R15	YOKOHAMA	7 mm
	R/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm
	L/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

	Accident Date	25/03/2018	**Inspection Date**	26/03/2018
	Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**

National Assessment Centre Services
51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6841 0055 FAX: 6841 6315
Reg. No: 52983356E GST Reg. No. 20-0405911-H

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5490E

Qty	Description of Parts	Condition	Estimate By Workshop ($)	Our Adjusted ($)
	REPLACEMENT OF PARTS			
1	COVER RR BUMPER ASSY (DISC 25%)	CUT	423.90	317.91
1	FILLER RR BUMPER RH (DISC 25%)	CRACKED	119.90	89.93
10	CLIPS PIECE FRT & RR BUMPER @$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	GUARD RR BUMPER LOWER (DISC 25%)	DEFORMED	558.30	418.73
1	COVER,GUARD RR BUMPER LOWER (DISC 25%)	CRACKED	14.80	11.10
1	REAR BUMPER REINFORCEMENT (DISC 25%)	DENTED	318.80	239.10
1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY (DISC 25%)	CRACKED	891.20	668.40
1	NAME PLATE (HYBRID) LUGGAGE COMPARTMENT (DISC 25%)	NECESSARY	52.30	39.22
1	NAME PLATE (PRIUS) LUGGAGE COMPARTMENT (DISC 25%)	NECESSARY	52.30	39.22
1	EMBLEM SUB-ASSY REAR (DISC 25%)	NECESSARY	46.30	34.71
2	PIXEL STICKER @$60.00 (SN)	NECESSARY	120.00	120.00
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
1	STICKER SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 65558888 (SN)	NECESSARY	21.60	21.60
2	PAD,RR BUMPER RH & LH,1 @$3.80	NOT NECESSARY	7.60	-
2	PAD,RR BUMPER RH & LH,2 @$3.80	NOT NECESSARY	7.60	-
2	PAD,RR BUMPER RH & LH,3 @$3.80	NOT NECESSARY	7.60	-
2	SEAL,RR BUMPER ARM RH & LH @$11.00	NOT NECESSARY	22.00	-
1	RETAINER,RR BUMPER RH	NOT NECESSARY	112.70	-
1	SEAL RR BUMPER RH	NOT NECESSARY	85.20	-
1	LENS & BODY ASSY,RR BUMPER,RH	NOT NECESSARY	486.80	-
3	PAD,RR BUMPER,CTR @$2.20	NOT NECESSARY	6.60	-
1	COVER,REAR FLOOR UNDER,RH	NOT NECESSARY	169.50	-
1	COVER,REAR FLOOR UNDER CENTER	NOT NECESSARY	222.60	-
1	TAIL GATE PANEL SUB-ASSY,BACK DOOR	NOT NECESSARY	929.60	-
1	LENS & BODY,REAR COMBINATION LAMP RH	NOT NECESSARY	438.10	-
			5,318.10	2,198.97

Report Ref No. NS/INC18005693/Stbe2

National Assessment Centre Services
51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6841 0055 FAX: 6841 6315
Reg. No: 52983356E GST Reg. No. 20-0405911-H

Qty	Description of Parts	Condition	Estimate By Our Workshop ($)	Our Adjusted ($)
	LABOUR			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		1,045.00	630.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		1,296.00	600.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,501.00	1,230.00
	GRAND TOTAL		**7,819.10**	**3,428.97**

RECOMMENDED COST OF REPAIRS (CONFIRMED) **3,428.97**

Report Ref No. NS/INC18005693/Stbe2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser