LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 05 Apr 2018

Preliminary Advice

Insured Vehicle No	: SJM6661R		
TP Vehicle No	: SLN7335Y	Accident Date	: 28/03/2018
Make	: TOYOTA PRIUS HYBRID	Assignment Date	: 03/04/2018
Date of Inspection	: 04/04/2018	Est. Duration of Repair	: 3.00
Inspection At	: WORLD AUTO PTE LTD - KRANJI (HQ) NO 1 KRANJI LOOP SINGAPORE 739535		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S$	2,567.50
Revised Amount	:S$	1,050.00
Check Items (Estimated)	:S$	0.00
Total	:S$	1,050.00
Lump Sum Repair	:S$	

Total Loss Consideration

New for Old Value	:S$	
Pre-Accident Value	:S$	
COE / PARF Rebate	:S$	
Salvage Value	:S$	
Margin for Repair	:S$	

Remarks

(   ) The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.