COMFORTDELGRO ENGINEERING PTE LTD AgAsia - LS TS

REPAIR ESTIMATE*

VEHICLE NO : SHA 6058U **DATE 4/4/2018**

MAKE :

MODEL : HYUNDAI SONATA LKK - Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid × repair			$ 1,349.50	
	Boot Lid Rubber ×			$ 110.90	
	Boot Lid Lock Upper ×			$ 132.10	
	Boot Lid Lock Lower ×			$ 30.30	
	Boot Lid Sonata Plate —			$ 43.60	
	Boot Lid Hyundai Plate —			$ 24.20	
	Boot Lid 'H' Emblem —			$ 26.10	
	Boot Lid CRDI Plate —			$ 22.70	
	Rear Bumper —			$ 578.40	
	Rear Bumper Reinforcement ?			$ 483.30	
	Rear Bumper Clip —			$ 22.00	
	Rear Bumper Sponge ?			$ 137.40	
	Rear Bumper Under Cover ?			$ 185.80	
	Rear Bumper Protector (LH/RH) × repair		$ 38.00	$ 76.00	
	Rear Panel × repair			$ 391.80	
	Rear Panel Garnish ?			$ 95.80	
	SUB TOTAL			**$ 3,709.90**	
	LESS 20%			$ 741.98	
	DISCOUNTED TOTAL			**$ 2,967.92**	
	Boot Lid Comfort Logo & Tel No. Sticker —			$ 30.00	**Nett**
	Boot Lid Advertisement Logo —			$ 100.00	**Nett**
	Rear Bumper Reverse Sensor —			$ 135.70	**Nett**
	Rear Bumper Advertisement Logo —			$ 50.00	**Nett**
	Rear Fender Advertisement Logo (LH/RH) —		$ 100.00	$ 200.00	**Nett**
				$ 515.70	
	Labour Charge Kalvin (LKK)				
	Panel Beating			$ ~~750.00~~ 400	
	Spray Painting Charge // 4/4/18 1.215hrs			$ ~~750.00~~	600
	Wiring Charges 3 Days			$ ~~50.00~~	×
	Turl Kote 4s			$ ~~50.00~~	×
	Remove/Refix Reverse Sensor After Repair pkt			$ ~~120.00~~	20
	TOTAL LABOUR			**$ 1,720.00**	
	ESTIMATE TOTAL			**$ 5,203.62**	

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To resurvey before/after replacement/repairing/resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.