LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

PDI TUAS

WU POH CHOO
53 CHOA CHU KANG LOOP
#09-31
Singapore, 689683
Singapore

PDI TUAS

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV031589
Quote No. SER/QUO/1800611
QuoteDate 10/04/18
Salesperson Darren Peh
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA TSI (DSG) HIGHLINE	68,855	Tang Shu Shi
License No.	**VIN**	**Initial Registration**	**Sales Advisor**
SKW3733Y	WVWZZZ16ZFM030162	27/10/15	Darren Peh
Engine Code	**Labor Type**	**Engine No.**	**Model Code**
	M4	CAX F52921	1634G5

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P MACP LABOUR	LABOUR	3	UNIT	840	~~2,520.00~~
P B&P MACP PAINT	SPRAY PAINT	3	UNIT	800	~~2,400.00~~
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		480.00
P B&P MECH	CHECK WIRE HARNESS, ECU, S Nett	1	Time Un		280.00
	Sum Labor				**5,680.00**
P 5C6807376	RHR BUMPER BRACKET	1	Pieces	?	83.31
P 5C6807421H GRU	REAR BUMPER Predecessor 5C6807417J GRU	1	Pieces	858	~~1,258.64~~
P 5C6945096H	TAILLIGHT RHR	1	Pieces	X	357.91
P 5C6945106B	RH REAR REFLECTOR	1	Pieces	50	53.98
	Sum Item				**1,753.84**

Rasul
Hp 90010068

3 days

16/04/18 @1405

Resurvey ~~after~~ repair by

Sum Labor			**5,680.00**
Sum Item			**1,753.84**
Total SGD			**7,433.84**
7% GST		7,433.84	520.37
Total SGD Incl. GST			**7,954.21**

Explanations
P = Proportionately Charged

Payment Terms No Credit

Payments to: - BBN: - Acc.-No..: