Allswell Motor Traders

25 Defu Lane 9, Singapore 539266
Tel : +65 6679 1146 email:ben@allswellmotor.com.sg

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

(3rd party claim against AXA Insurance GBA2693D)

Estimate repair

Vehicle No. : SLH4393E
Make & Model : Toyota Axio Hybrid
Chassis No. :
Date of survey :

Submitted by : Ben
COE expiry : end 2026
Engine No. :

S/No	Part Description	Qty	Unit Price	Price	Disposition by
	Parts description.				
01	LH shock absorber / BT	01	$999.3	~~$999~~ /	
02	LH front fender / Inc	01	$595.2	/	
03	LH front fender inner shield / ~~Rel~~ RL	01	$291-1	161.6	
04.	L/H Front lower arm / BT special left.	01	$478-1	/	
05	L/H inner shield clips ⑤ / ALC $11.00 each	02	$22-0	/	
	Labour description.				
01	Dismantle / assembly of lower arm & shock absorber	01	$260	200	
02.	Dismantle and assembly of R/H fender and inner panel	01	$260	200	
03.	spray painting on effected part LH fender & LH front door	01	$660	$400	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

1756.2
25% : 1317.15
800
217.15

4 Days.