LKK ... tants hence notify the ... pairer ... the following:
- Tr... esurvey be... after spray painting
- ... display ... part(s) during resurvey
- Parts prices are ... ject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to ... nal approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tan Jun 97495744
WP'
23/4/18 @ 1110
Resuvey before paint
6days
sun@lkkauto.com.sg

PDI TUAS

PDI TUAS

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

CHUA YINGLIN
(CAI YINGLIN)
33 TAMPINES CENTRAL 7
#15-47
Singapore, 528614
Singapore

Service Quote

Customer No.	CV037804
Quote No.	SER/QUO/1800659
QuoteDate	16/04/18
Salesperson	Angie Tan
Page	1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	SPORTSVAN 1.4 TSI CL	11,051	Kong Charmaine
License No.	**VIN**	**Initial Registration**	**Sales Advisor**
SLQ1338M	WVWZZZAUZGW563923	28/06/17	Angie Tan
Engine Code	**Labor Type**	**Engine No.**	**Model Code**
	1T	CZC 086160	AM13HZ

	No.	Description	Qty.	UoM	Unit Price	Amount
P	B&P ALEX LABOUR	R&R REAR WINDSCREEN	1	UNIT		840.00
P	B&P ALEX LABOUR	LABOUR	5	UNIT		2100 4,200.00
P	B&P ALEX LABOUR	TRANSFER BOOT MECHANISM P	1	UNIT		420 840.00
P	B&P ALEX PAINT	SPRAY PAINT	4	UNIT		1600 3,200.00
P	B&P SENSOR	SUPPLY & INSTALL REVERSE SE	1	Pieces		nw 400.00
P	B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		480.00
P	B&P MECH	COMPULSORY TO DO AFTER AC CHECK WIRE HARNESS, ECU, S Nett	1	Time Un		280.00
		Sum Labor				**10,240.00**
P	510071360	BOOT CHROME STRIP, SPORTV	1	Pieces		dw 149.22
P	3CN945087	BRAKELIGHT	1	Pieces		? 204.88
P	510805945 041	BOOTLID SPOILER TRIM LH	1	Pieces		nw 96.45
P	510805946 041	BOOTLID SPOILER TRIM RH	1	Pieces		nw 92.82
P	510807393A	BUMPER BRACKET LH	1	Pieces		? 75.84
P	510807393C	BUMPER GUIDE LH	1	Pieces		? 74.52
P	510807394A	BUMPER BRACKET RH	1	Pieces		75.84
P	510807394C	BUMPER GUIDE RH	1	Pieces		74.52
P	510807417M GRU	REAR BUMPER COVER Predecessor 510807417J GRU	1	Pieces		dw 1,387.99
P	510807863A	STRIP	1	Pieces		nw 62.25
P	510827025AA	LID Predecessor 510827025T	1	Pieces		nw 1,960.84
P	510827705A	BOOT SEAL/GASKET	1	Pieces		nw 360.00
P	510853675P CWB	NAME PLATE BLUEMOTION TEC	1	Pieces		nw 88.83
					Sum carried forward	**14,944.00**

Payments to: - BBN: - Acc.-No..:

PDI TUAS

Phone No.
Fax No.
E-Mail

PDI TUAS

CHUA YINGLIN
(CAI YINGLIN)
33 TAMPINES CENTRAL 7
#15-47
Singapore, 528614
Singapore

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV037804
Quote No. SER/QUO/1800659
QuoteDate 16/04/18
Salesperson Angie Tan
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	**Model Description**	**Mileage**	**Service Advisor**
Volkswagen Passeng	SPORTSVAN 1.4 TSI CL	11,051	Kong Charmaine
License No.	**VIN**	**Initial Registration**	**Sales Advisor**
SLQ1338M	WVWZZZAUZGW563923	28/06/17	Angie Tan
Engine Code	**Labor Type**	**Engine No.**	**Model Code**
	1T	CZC 086160	AM13HZ

			Continued	**14,944.00**
P 510853675S 2ZZ	NAME PLATE 230TSI	1	Pieces	62.55
P 510853687E 2ZZ	NAME PLATE "GOLF"	1	Pieces	88.83
P 510945093L	TAILLIGHT LH INNER	1	Pieces	286.29
P 510945095R	TAILLIGHT LH OUTER	1	Pieces	261.57
P 5G6807568D 9B9	REAR DIFFUSER	1	Pieces	322.86
	Use Predecessor 5G6807568D			
P 5G9807305A	BUMPER REINFORCEMENT	1	Pieces	460.17
P D 004660M2	2K GLUE	1	Pieces	183.87
P D 00920002	PRIMER	1	Pieces	32.19
P D 00940104	CLEANER	1	Pieces	113.83
	66H3 Service Campaign (GOLF)			
P D 00950025	APPLICATOR	2	Pieces	22.38
P D 181802M1	ACTIVATOR	1	Pieces	29.46
	Sum Item			**6,568.00**

Sum Labor	**10,240.00**
Sum Item	**6,568.00**

Total SGD		**16,808.00**
7% GST	16,808.00	1,176.56
Total SGD Incl. GST		**17,984.56**

Explanations
P = Proportionately Charged

Payment Terms No Credit

Payments to: - BBN: - Acc.-No..: