COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

AIG
LKK
JU

VEHICLE NO : SHD 4354L DATE 26/4/2018 11:32

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Bonnet X hg 2v			$ 1,151.80	
	Front Bumper Cover – Detrauld			$ 538.80	
	Front Bumper Sponge X SUK			$ 136.30	
	Front Bumper Reinforcement X SUK			$ 504.10	
	Front Bumper Bracket Top (LH) X SUK			$ 22.40	
	Front Bumper Protector (LH) X SUK			$ 29.20	
	Front Bumper Bracket (LH) X SUK			$ 20.10	
	Headlamp Support Panel Assy X SUK			$ 1,023.00	
	Headlamp (LH) – CRA			$ 797.90	
	Front Fender (LH) – Ret			$ 593.00	
	Front Fender Shield (LH) X SUK			$ 86.00	
	Front Fender Retainer X SUK			$ 9.20	
	Front Wheel Hub Cap (LH) X SUK			$ 145.00	
	SUB TOTAL			**$ 5,056.80**	
	LESS 20%			$ 1,011.36	
	DISCOUNTED TOTAL			**$ 4,045.44**	
	Front Fender Advertisement Logo (LH) – NE			$ 100.00	Nett
				$ 100.00	
	Labour Charge				
	Panel Beating			$ ~~850.00~~ 400	
	Spray Painting Charge			$ ~~600.00~~ 540	
	Wiring Charge			$ ~~50.00~~ 20	
	Tuff Kote			$ ~~50.00~~ 20	
	FRT Wheel Alignment			$ ~~120.00~~ X NA	
	Remove/Refix Aircon & Refill Gas			$ ~~150.00~~ X NA	
	TOTAL LABOUR			**$ 1,820.00**	
	ESTIMATE TOTAL			**$ 5,965.44**	

Kalvin
26/4/18 1370h.
3 Days
4/5 After Repair

LKK Auto C... notify the Repair... following:
- To resurve...
- To display ...
- Parts prices
- Third party su...
- No illegal mod...
- Supplementary ...
- Subject to fina...

...er spray painting
...during resurvey
...information
...Prejudice" basis
...ed
...surveyed and
...Insurance Company

Authorised Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.