Broker: Tanfah | REF: ASM(AXA) 9149

ASSIGNMENT

From: | Date: 24/05/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLP 4006G

at Workshop m/s: Kah Motor

of: 15 Ubi Rd 4

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh:

11am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	

Bal. or Market Value: $93K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: SLP4006G | Yr Regn: 2017 June.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Civic 1.6 | C.C: 1597

Colour: Grey | A/C: Insured / Std / NI / NA

Sp.Reading: 13245 | T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MRH FC565 0GT 001488

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/50R16

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Hankook.

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	24/5/18

Survey held at: Kah Motor Ubi

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time File Pass to? 1) ☐ : Preli. Report ☐ : Final Report

Date/Time File Return to? 2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp ($) ☐ Interview ($) ☐ Tech. Invs ($) ☐ Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:

Transportation: $ + RS SI

Photos

Others

TOTAL