	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	AC (P/
		11	1			Headlamp Top Panel RH (Metal)			Serviceable	0				0	Re
		12	1			Front Grille }			Cut	185				185	Re
		13	1			Front Grille Logo }				0				0	Re
		14	10			Front Grille Clip			Necessary	1.5				15	Re
		15	1			Front Bumper			Deformed	485				485	Re
		16	10			Front Bumper Clip			Necessary	1.5				15	Re
		17	1			Front Bumper Side Retainer LH			Necessary	18				18	Re
		18	1			Front Bumper Side Retainer RH			Serviceable	0				0	Re
		19	1			Front Number Plate Base			Serviceable	0				0	Re
		20	1			Front Bumper Foam			Serviceable	0				0	Re
		21	1			Front Bumper Upper Beam			Bent	68				68	Re
		22	1			Front Bumper Reinforcement			Bent	300				300	Re
		23	1			Support Panel			Serviceable	0				0	Re
		24	1			Condenser Side Cover LH			Serviceable	0				0	Re

Detailed Assessment

Inspection Date *

05/23/2018

Total Loss

Yes **No**

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good

Steering (Serviceable)

Yes **No**

Footbrake (Serviceable)

Yes **No**

Handbrake (Serviceable)

Yes **No**

Engine Modification

Yes No

Pre-accident condition

-- none --

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

205/55R16

Rear Tyre Size

205/55R16

FNOL INFORMATI...	50J FABER HEIGHTS, #01-67 FABER CREST, 129203, Singapore
POST SURVEY INF...	
CATEGORY	Address type
FNOL INFORMATI...	Personal Correspondence
POST SURVEY INF...	
CATEGORY	Gender
FNOL INFORMATI...	Male
POST SURVEY INF...	
CATEGORY	Marital status
FNOL INFORMATI...	Married
POST SURVEY INF...	
CATEGORY	Identification #
FNOL INFORMATI...	S2711938G

CATEGORY	Make
POLICY INFORMAT...	VOLKSWAGEN
ASSESSMENT INFO...	VOLKSWAGEN
CATEGORY	Model
POLICY INFORMAT...	JETTA 1.4
ASSESSMENT INFO...	JETTA 1.4 TSI AT 1622G5
CATEGORY	Type
POLICY INFORMAT...	
ASSESSMENT INFO...	
CATEGORY	Type of Paint
POLICY INFORMAT...	
ASSESSMENT INFO...	
CATEGORY	Chassis No
POLICY INFORMAT...	WVWZZZ16ZCM135766

CATEGORY	Date of Birth
FNOL INFORMATI...	November 24, 1967
POST SURVEY INF...	mm/dd/yyyy
CATEGORY	Age
FNOL INFORMATI...	50
POST SURVEY INF...	
CATEGORY	Occupation
FNOL INFORMATI...	Unknown
POST SURVEY INF...	
CATEGORY	Education Qualification
FNOL INFORMATI...	Other
POST SURVEY INF...	
CATEGORY	Driving Experience

Accelerated
workshop survey

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Messages Invoices History Documents

Assessment Metrics Notes Add

Additional Instructions

EXCESS - WAIVED NO ESTIMATES YET
ETHOZ - BT BATOK

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	6/5/18 10:36 AM	3091	3091	Approved	Share	Clone
ANG Richard	5/23/18 9:25 AM			Open	Share	Clone

Accelerated
workshop survey

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Messages Invoices History Documents

Assessment Metrics Notes

Additional Instructions

EXCESS - WAIVED NO ESTIMATES YET
ETHOZ - BT BATOK

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
SUPPLEMENTARY.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	June 5, 2018
RESURVEY PHOTOS.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	June 5, 2018
SURVEY PHOTOS.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	May 24, 2018