Surveyor Rajah | REF: AIG | 9840/pa3 (P) | 41580

ASSIGNMENT

From: Date: 06062018

Estimated Cost:

OD / TPY WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKS 4381T

at Workshop m/s Volkswagen

of 1 Kampong Ampat off Macpherson Rd.

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition) 3pm owner waiting

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKS 4381T Yr Regn: 2015 / APR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: VOLKSWAGEN GOLF A7 1.4 c.c 1395

Colour WHITE A/C: Insured / Std / NI / NA

Sp.Reading 71016 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVWZZZAUZFW 063077

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A. 29/05/18 D.O.I. 06/06/18

Survey held at VOLKSWAGEN Kh Ampat

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

b/s FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:

Transportation: ___S + RS, ___SI

Photos

Others

TOTAL