22/03/2003

ASS. REC. BY: | REF: CS3 | AGI18009957/G24 dB SV Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): Julie Mengubat of AGI Date/Time: 1/6/18 @ 10:27am

Estimated Cost: Bill to:

OD / (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBG 1605M Insured: SJC 98UP

at Workshop m/s Gee Seng Motor Tel: 6747 2429

of B/Kit, Kaki Bukit Ave 3 #01-69

Policy No: Claim No: C10001637/JM

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 28/05/2018

CA / REV / REP. / REV 24 HRS lup?

H.O.D. Endorsement:

Date/Time: 11:54am @ 1/6/18 Person Contacted: Seng Vehicle (IN) / OUT

Date/Time	Action/Instruction
	(x) Estimate
	GBG1605M-x
	SJF 98UP-x
01-06-18	Dismantle
4/6/18	Dismantled

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

D.O.A. D.O.I. 01-6-18

Survey held at W/S 12:30pm

Des. of Damages : Frt / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Estimated repair range $6,500 – $8,000
	21/6/2018

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:

Transportation: ___S + RS.___SI

Photos

Others

TOTAL