LIM TAN MOTOR

ESTIMATE TO REPAIR

SURVEYOR NAME	:
DATE OF SURVEY	: 11. 06. 2018
TIME OF SURVEY	:

VEHICLE NO. : SLR 9687 Y
MAKE : TOYOTA
MODEL : VIOS E AUTO
YEAR : 2008
CHASSIS NO : MR053HY9305072404

DATE : 5-Jun-18
DATE OF ACCIDENT : 28-May-18
THIRD PARTY REF : SFX 57 P / AXA

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				$ 538.40
1 pc	Rear Bumper Lower Spoiler			CRP	$ 525.40
2 pcs	Rear Bumper Retainer		$ 87.40		$ 174.80
1 pc	Rear End Panel				$ 658.16
1 pc	Rear Boot VIOS Emblem				$ 78.70
1 pc	Rear Boot E SPORTS Emblem				$ 75.40
					$ 2,050.86
	Less 25%				$ 512.72
					$ 1,538.15
1 set	Rear Bumper Reverse Sensor	S.Nett			$ 200.00
	To putty & spray painting.				$ 700.00
	To anti rust.				$ 50.00
	Labour Charges.			200	$ 600.00
TG-RA/-	**TOTAL**				**$ 3,088.15**

Not Without
L/Sup &
Survey After Paint
2days

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Lim Tan Motor Pte Ltd
Blk [illegible] Drive #03-09 Sin Ming Autocare Singapore 575721
Tel:65-64[illegible] Website www.LTM.sg
Co [illegible] GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd