COMFORTDELGRO ENGINEERING PTE LTD

Air Asia - 4S TS

REPAIR ESTIMATE*

VEHICLE NO : SHB 4322P **DATE 6/6/2018**

MAKE :

LKK - Kalvin

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper X Hyundai			$ 603.60
	Rear Bumper Reinforcement ?			$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ?		$ 180.00	$ 360.00
	Rear Bumper Clips 10 pcs X			$ 22.00
	Rear Bumper Sponge ?			$ 143.40
	Rear Bumper Under Cover ✓			$ 225.00
	SUB TOTAL			**$ 1,858.35**
	LESS 20%			$ 371.67
	DISCOUNTED TOTAL			**$ 1,486.68**
	Labour Charge			
	Panel Beating (Repair)			$ ~~350.00~~ 200
	Spray Painting Charge			$ ~~250.00~~ 200
	TOTAL LABOUR			**$ 600.00**
	ESTIMATE TOTAL			**$ 2,086.68**

Kalvin LKK
6/6/18 1430hrs
2 Days
4S
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: