N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub
2 Kaki Bukit Ave 2
#01-17 / #01-18 /Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921
Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

Grab Rentals Pte Ltd
18 SIN MING LANE #01-18
MIDVIEW CITY
Singapore 573960

Contact: 66550005 96603709

Repair Code: CLM14576
Date in: 07/06/2018
Vehicle No.: SLR5043G
Model: HONDA VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD
Chassis/Eng#: RU31234471/LEB5934485

SUPPLEMANTARY ITEMS

No	Description Of Parts		Qty	Unit Price	Amount
1	Steering Rack & Pinion ~~bkt~~ xtl new	L	1	$ 1,173.00	$ 1,173.00
	xtl New				
	Sub total before discount:				$ 1,173.00
	Percentage discount 20%:				$ 234.60
	Sub-total :				$ 938.40
	Parts Total:				**$ 938.40**

parts $5,441.60
s.nett $ 80
Labour $1,100
$6,621.60
-20% $1,324.32
$5,297.28
≈ $5,300 L/S

Scan – @ 6421.60
S.nett @ 780.00
Labour @ 1370.00
Supply @ 938.40
@ 9510.00
c/s – 20% @ 1902.00
@ 7608.00

L/S repair @ 7608.00

No. of Repair Days : 5

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: