CITY CAB PTE LTD

REPAIR ESTIMATE*

A29

VEHICLE NO : SHC 501K **DATE 12/6/2018 14:37**

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper × Repair			$ 578.40	
	Rear Bumper Reinforcement ?			$ 483.30	
	Rear Bumper Clip ×			$ 22.00	
	Rear Bumper Sponge ?			$ 137.40	
	Rear Bumper Under Cover ×			$ 185.80	
	Rear Bumper Protector (LH/RH) ×		$ 38.00	$ 76.00	
	SUB TOTAL			**$ 1,482.90**	
	LESS 20%			$ 296.58	
	DISCOUNTED TOTAL			**$ 1,186.32**	
	Rear Bumper Reverse Sensor ×			$ 135.70	**Nett**
				$ 135.70	
	Labour Charge				
	Panel Beating			$ ~~350.00~~ 100	
	Spray Painting Charge			$ ~~250.00~~ 200	
	R/Refix Reverse Sensor			$ ~~150.00~~ ×	
	TOTAL LABOUR			**$ 750.00**	
	ESTIMATE TOTAL			**$ 2,072.02**	

Kalvin LKK

12/6/18 1520 hrs

2 hrs

L/S

After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.