(08/11/13)

Surveyor: Rasul

REF:

25740

# ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJX 3261X

at Workshop m/s CHARN'S CUSTOMCRAFT

of 1010, BUKIT MERAH #01-105

Insured: AXA

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition) 3pm

Remark: **The veh had commenced its repair at the time of inspection.**

| N/S | O/S |
|---|---|
| | |

Bal. or Market Value: 25K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJX 3261Z Yr Regn: 2010 / Jun

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: HONDA CIVIC 1.6L c.c 1595

Colour GREY A/C: Insured / Std / NI / NA

Sp.Reading 151773 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMFD4620952007 03

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: " "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

| Front | | Rear | |
|---|---|---|---|
| R/Bal. 5 | mm | R/Bal. 5 | mm |
| L/Bal. 5 | mm | L/Bal. 5 | mm |
| D.O.A. 11/06/18 | | D.O.I. 10/07/18 | |

Survey held at CHARN'S CUSTOMCRAFT

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or N/S FRT & N/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|---|---|
| | |

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: ($ )

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($ )

☐ : Interview ($ )

☐ : Tech. Invs ($ )

☐ : Weekend ($ )

Survey Fee:

Transportation: ___S + RS, ___SI

Photos

Others

TOTAL