New Union Company

GST Reg No. M90370043N

9004 Tampines Street 93 #01-106
Singapore 528838

P: 67849488
F: 67847588

Email: numotor@singnet.com

Attn: To Whom Concern
Address: -
-

Phone:
Fax:
Email:

Quotation No. #:26_07_2018_I
Quote Date:

Quotation For: Bike Repair - FBJ5842C

Item #	Description	Qty	Unit Price	Discount	Price
1	Crash Bar Assy, Top & Bottom bt✓	1	$ 750.00		$ 750.00
2	Rack for Box dd✓	1	250.00		$ 250.00
3	Handle Bar bt✓	1	95.00		$ 95.00
4	Hand Guard Assy cut✓	1	185.00		$ 185.00
5	Balancer ✗ nn	2	35.00		$ 70.00
6	Wind Shield cua✓	1	250.00		$ 250.00
7	Front No. Plate new✓	1	25.00		$ 25.00
8	Footrest Bracket, Front cut✓	1	130.00		$ 130.00
9	Gear Pedal cut✓	1	145.00		$ 145.00
10 L	Fork Press	1	120.00	✓	$ 120.00
11	Front Fender cut✓	1	160.00		$ 160.00
12	Front Wheel Shaft ✗ nn	1	45.00		$ 45.00
13 L	Front Rim Press	1	80.00	60.	$ 80.00
14	Corn Steer Bearing new✓	1	120.00		$ 120.00
15 L	Tank Repair	1	120.00	100.	$ 120.00
16 L	Spray Paint	1	280.00	200.	$ 280.00
17	Front wheel Bearing new✓	2	23.00		$ 46.00
18 L	Labor Charge	1	250.00	200.	$ 250.00
					$ -
				Sub-Total	$ 3,121.00
				Tax Rate	7.00%
				GST	218.47
				Other	
				Grand Total	3,339.47

Customer Signature

Make all checks payable to New Union Company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Parts - 2156
10% - 1940.40.
Labour - 680
2620.40.
4/5 $2100
04 days #