(08/11/13)

Surveyor:

REF: Alh

ASSIGNMENT

From: Date: 26062018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKM 155M

at Workshop m/s Jin Auto

of 14 Defu Lane 10 # 01-412

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 20k

IDAC Accident Rport: Consistent? : Yes or No

CA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No 23/4/2021

CA / REV / REP. / 24 HRS LTA 12965 Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKM155M Yr Regn: 4 / 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or GM /

Make: M.Y Lancer c.c 1584

Colour white A/C: Insured / Std / NI / NA

Sp.Reading 269338 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JMYSNCS3A6U004981

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185-/55-R15-

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	23/6/18	D.O.I.	26/6/18

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear & Rl.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	2yrs. 10mk. next 703K

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:

Transportation: __S + RS, __SI

Photos

Others

TOTAL