ABWIN 諭煇

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Date	: 25/06/2018
TP Vehicle No.	: SLR-8004-A
To	: **AIG ASIA PACIFIC INSURANCE PTE LTD**
Attn	: **Motor Claim Department**

Owner	: SENTOSA DEVELOPMENT CORPORATION
	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No.	: 5084105925-01
Vehicle No.	: RU -4649-D
Make & Model	: MITSUBISHI L200 DOUBLE CABIN 2.5L TURBO 4A/T DIESEL

Accident Date: 05/05/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
List Item			
1	TAILGATE	$3,500.60	
1	TAILGATE LOCK CATCH RH	$295.60	
1	TAILGATE LOCK CATCH LH	$295.60	
1	TAILGATE EMBLEM "L200"	$120.30	
1	TAILGATE EMBLEM "MITSUBISHI"	$200.60	
1	TAILGATE STOPPER RH	$165.60	
1	TAILLGATE STOPPER LH	$165.60	
1	TAILLAMP RH	$450.60	
1	TAILLAMP LH	$450.60	
	Sub Total	**$5,645.10**	
	Discount 30% on Parts	**($1,693.53)**	
		$3,951.57	
Special Nett			
1	TAILGATE ADVERTISMENT STICKER	$1,200.00	
1	TAILGATE STEP PANEL	$3,500.00	
1	TAILGATE NUMBER PLATE LAMP	$250.60	
	Sub Total	**$4,950.60**	
Labour & Misc			
	TO STRAIGHTEN AND PANEL BEAT ACCIDNET AREAS	$1,800.00	
	TO SPRAY PAINT ON AFFECTED AREAS	$1,500.00	
	TO TRANSFER ALL REAR TAILGATE FITTING	$250.00	
	TO CHECK LIGHTING AND FOCUS TAILLAMP	$250.00	
	TO TRANSFER TAILGATE STEP PANEL COMPOENTS	$250.00	
	Sub Total	**$4,050.00**	
	Sub Total	**$12,952.17**	
	GST 7%	**$906.65**	
	Total	**$13,858.82**	

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Date	: 25/06/2018
TP Vehicle No.	: SLR-8004-A
To	: **AIG ASIA PACIFIC INSURANCE PTE LTD**
Attn	**: Motor Claim Department**

Owner	: SENTOSA DEVELOPMENT CORPORATION
	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No.	: 5084105925-01
Vehicle No.	: RU -4649-D
Make & Model	: MITSUBISHI L200 DOUBLE CABIN 2.5L TURBO 4A/T DIESEL

Accident Date: 05/05/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.