ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A
#03-11 AMK Autopoint Singapore 568047
Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

Not Workshop
Running After Paint
3 days

India International Insurance Pte Ltd
64 Cecil Street
#05 IOB Building
Singapore 049711
Attn: Motor Claims Department

Date :	26/06/2018
Vehicle No :	SLS9062U
Veh Make/Model :	Mercedes Benz B200
YOM :	2013
Chassis No :	WDD2462432J204294
Date of Accident :	25/06/2018

No	Qty	Description	Amount $	
		List Items:-		
1	1	Front RH fender	$ R 648.00	X
2	1	Front RH fender splash shield	$ Sn 184.00	X
3	10	Front RH fender splash shield clips	$ nn 90.00	X
4	1	RH side mirror assy	$ R 1,013.00	X
5	1	Front RH door assy	$ R 1,570.00	X
6	1	Front RH door pillar garnish	$ Sn 259.60	X
7	1	Front RH door outer chrome	$ Sn 170.00	X
8	1	Rear RH door assy	$ R 1,685.00	X
9	1	Rear RH door pillar garnish	$ Sn 259.60	X
10	1	Rear RH door outer chrome	$ Sn 133.00	X
11	1	Front RH shock absorber	$ Sn 647.00	X
12	1	Front RH shock absorber mounting	$ Sn 282.00	X
13	1	Front RH shock absorber stopper	$ Sn 54.00	X
		Total - List Item	**$ 6,995.20**	
		Less 10%	**$ 699.52**	
		Total	**$ 6,295.68**	
		Special Nett Items:-		
1	1	Front RH wheel rim (Dd)	$ N.C 1,080.00	X
2	1	Front RH tyre	$ Sn 420.00	X
		Total - SN Item	**$ 1,500.00**	
		Balance b/f	**$ 7,795.68**	

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A
#03-11 AMK Autopoint Singapore 568047
Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

India International Insurance Pte Ltd
64 Cecil Street
#05 IOB Building
Singapore 049711
Attn: Motor Claims Department

Date :	26/06/2018
Vehicle No :	SLS9062U
Veh Make/Model :	Mercedes Benz B200
YOM :	2013
Chassis No :	WDD2462432J204294
Date of Accident :	25/06/2018

No	Qty	Description	Amount $	
		Balance c/f	**$ 7,795.68**	
		Labour Charges:-		
1		Spray painting on all affected area.	$ 1,400.00	50%
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	$ 1,500.00	20%
3		To apply anti rust treatment.	$ 180.00	
4		To check front RH door, rear RH doo, side mirror wiring system.	$ 100.00	20
5		To check & adjust front wheel aligment.	$ 120.00	X
6		To remove and replace front RH suspension.	$ 300.00	X
7		To transfer front RH door mechanism.	$ 150.00	X
8		To transfer rear RH door mechanism.	$ 150.00	X
		Total - L/C	**$ 3,900.00**	
		Sub-Total	**$ 11,695.68**	
		7% GST	**$ 818.70**	
		Total	**$ 12,514.38**	