LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 02 Jul 2018

Preliminary Advice

Insured Vehicle No	: SLJ4562Z		
TP Vehicle No	: SDL8138Z	Accident Date	: 27/06/2018
Make	: MITSUBISHI LANCER	Assignment Date	: 28/06/2018
Date of Inspection	: 28/06/2018	Est. Duration of Repair	: 0
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S$	3,631.50
Revised Amount	:S$	1,245.00
Check Items (Estimated)	:S$	1,540.80
Total	:S$	2,785.80
Lump Sum Repair	:S$	

Total Loss Consideration

New for Old Value	:S$
Pre-Accident Value	:S$
COE / PARF Rebate	:S$
Salvage Value	:S$
Margin for Repair	:S$

Remarks

( ) The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.