Mail on 02.07
1733hr

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

FWD Insurance Insured's Veh No : SLX9978B
Date of Accident : 01 July 2018

Not Allowed due
L/S $2100
4 days.
4/7/18
They have Other Nyc

Miss Teo Beng Swan Janet

Date : 02 July 2018

LKK - Marcus
04/07/18 01100 hp

Estimate To Repair SKU1231C - Honda FIT 1.3G CVT ABS D/AIRBAG 2WD
Chassis No : GK31015870

S/No	Quantity	Description	Amount	
		LIST ITEMS		
01	1 pc	o/s front fender so dsm Delivered	$ 435.00	—
02	1 pc	front fender inner liner	$ 71.50	—
03	4 pc	front fender inner liner clips @ $3.50 "	$ 14.00	—
04	1 pc	front fender air baffle "	$ 18.00	X
05	1 pc	o/s front door DD/Sy	$ 757.00	—
06	1 ps	front door window frame matt tape sticker "	$ 30.50	—
07	1 pc	front door outer weatherstrip molding "	$ 43.90	X
08	1 pc	front door window glass channel weatherstrip "	$ 33.10	X
09	1 pc	o/s front shock absorber "	$ 310.00	X
10	1 pc	front shock absorber top mount "	$ 36.80	X
11	1 pc	front wheel bearing "	$ 168.00	X
12	1 pc	front wheel bearing with hub "	$ 138.30	X
13	1 pc	front lower arm "	$ 160.00	X
14	1 pc	front wheel kunckle "	$ 230.00	X
			$ 2,446.10	1308
		Less 20 %	$ 489.22	1046.4
			$ 1,956.88	
		SPECIAL NETT ITEMS		
15	1 pc	o/s front wheel rim CW	$ 500.00	400 S.N
16	1 pc	front wheel tyre SW	$ 350.00	X
			$ 850.00	
		LABOUR & MISC. CHARGES		
01		To transfer of o/s front door fittings and perform water seepage test.	$ 180.00	60
02		To rust-proofing of the affected areas.	$ 150.00	60
03		To check electrical lighting concerned.	$ 40.00	20
04		To drop o/s front suspension undercarriage parts, remove and renewal of the necessary parts, to perform final checking and testing.	$ " 300.00	X
05		To check steering geometry and computer wheel alignment.	$ 150.00	60
06		To transfer of o/s front tyre, rim and on wheel balancing.	$ " 50.00	X
07		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	$ 550.00	400
08		Putty and spray painting of the affected portion.	$ 780.00	600
			$ 2,200.00	2646.4
		Total	$ 5,006.88	2117

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: