Not Approval
rbu
r/p @ 6102.85
3/7/18
4 day.

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6
#01-46/48/50 Autobay
SINGAPORE 417883

VEHICLE NO:GBH 4157P

QTY	PARTICULAR			AMOUNT
1 PCS	TAILGATE	*2145-10*	*Body.o*	$2,466.10
1 PCS	TAILGATE REAR LOGO		*ru*	$68.10
1 PCS	TAILGATE TOYOTA STICKER		*ru*	$56.50
1 PCS	TAILGATE 'HIACE STICKER		*ru*	$52.50
1 PCS	TAILGATE INNER LOCK		*1m/ditt*	$395.40
1 PCS	TAILGATE LOCK STICKER		*11*	$66.50 X
1 PCS	TAILGATE INNER TRIM BOARD		*neyed*	$485.10
1 SET	TAILGATE INNER TRIM BOARD CLIPS		*ru*	$50.00
1 PCS	TAILGATE WEATHERSTRIP	*352.10*	*1ml*	$429.10
2 PCS	TAILLAMPS @$450.00	*386.10 x 2 = 772.20*	*cru*	$900.00
2 PCS	TAILLAMP LOWER GARNISH @$115.00		*11*	$230.00 X
1 PCS	TAILGATE OUTER HANDLE		*grand*	$366.20
1 PCS	TAILGATE LOCK ACTUATOR		*Slhd/fn*	$325.50
1 PCS	REAR BUMPER	*645.10*	*ro/pe*	$788.10
2 PCS	REAR BUMPER LOWER BRACKETS @$25.00		*n*	$50.00 X
1 SET	REAR BUMPER CLIPS		*ru*	$50.00
1 PCS	REAR END PANEL OUTER		*n*	$699.10 X
1 PCS	REAR END PANEL INNER	*25%*	*n*	$1,029.30 X
1 PCS	REAR WINDSCREEN		*11*	$1,650.00 X
		5803.80		$10,157.50
	S.NETT			
1 SET	REAR BUMPER REVERSE SENSOR		*shut*	$280.00 *200*
1 PCS	REAR WINDSCREEN SEALANT		*ru*	$50.00 *40*
1 PCS	REAR WINDSCREEN INNER SEAL		*ru*	$50.00 *30*
1 PCS	REAR '70KM/H' STICKER		*ru*	$20.00 *10*
	LABOUR CHARGES:			
	TO CHECK WIRING	*reverse*		$50.00 *20*
	TO DISMENTLE & REPLACING PDC SENSOR			$80.00 *50*
	TO DISMENTLE & REFIX REAR WINDSCREEN			$150.00 *120*
	TO DISMENTLE & REFIX TAILGATE COMPONENTS			$120.00 *60*
	TO SPRAY RUST PROOFING			$100.00 *40*
	LABOUR FOR PANEL BEATING & REPLACING PARTS			$880.00 *500*
	TO PUTTY & SPRAY PAINTING			$1,280.00 *680*
			TOTAL	$13,217.50