COMFORTDELGRO ENGINEERING PTE LTD AIG

REPAIR ESTIMATE*

VEHICLE NO : SHD 4909L **DATE 5/7/2018 10:28**

MAKE :

MODEL : HYUNDAI i40 L/S DOA: 05.07.18

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper			$ 603.60	/ check
	Rear Bumper Reinforcement			$ 504.35	?
	Rear Bumper Reinforcement Bracket (LH/RH)		$ 180.00	$ 360.00	?
	Rear Bumper Side Bracket			$ 49.00	?
	Rear Bumper Clips			$ 22.00	/ rec
	Rear Bumper Sponge			$ 143.40	?
	Rear Bumper Under Cover			$ 225.00	X SVC
	SUB TOTAL			**$ 1,907.35**	
	LESS 20%			$ 381.47	
	DISCOUNTED TOTAL			**$ 1,525.88**	
	Rear Bumper Reverse Sensor			$ 135.70	**Nett** X SVC
	Rear Bumper Rubber Mat			$ 50.00	**Nett** / rec
				$ 185.70	
	Labour Charge				
	Panel Beating			$ ~~350.00~~	200
	Spray Painting Charge			$ ~~250.00~~	200
	Wiring Charge			$ ~~50.00~~	20
	R/Refix Reverse Sensor			$ ~~120.00~~	20
	TOTAL LABOUR			**$ 770.00**	
	ESTIMATE TOTAL			**$ 2,481.58**	

NAZ LKK
5/7/18 1600
L/S
2 days
After repair photo

LKK Auto Consultants hence notify the Repairer [illegible] following:
- To resurvey before/after [illegible] painting
- To display damage [illegible] during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.