ASS. REC. BY: | REF: CS/EGI18012742 / Kvd3 | Special Instruction: NZ

Surveyor: Kenneth ASSIGNMENT (Office)

From (Person): Yee Pei Li of EGI Date/Time: 13/07/2018 @ 9.46am

Estimated Cost: Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: EZ 4428C Insured: GBG 8186J

at Workshop m/s: Lai Huat (Meng Kee) Tel: 6453 8110

of: Blk 160 Bin Ming Drive #04-01

Policy No: Claim No: DSMCV1801347 / SL / PI

Sum Insured: Excess:

Make of Veh: D.O.A. 09/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'up' H.O.D. Endorsement:

Date/Time: 13/7/18 @ 9.50am Person Contacted: Jenny Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	EZ 4428C - X
	GBG 8186J - X.
16/7/18	10.39am - vehicle still not in yet. called jenny.
25/7/18	Revert thm email
10/8/18	@ 4.24pm Jenny will email us finalised

ASS. REC. BY: Kenneth | REF: EG21

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s LIMK

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: EZ 4428C Yr Regn: 04 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or Wagon

Make: Volvo V70 T5 c.c 2521

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp.Reading 195749 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: YV1BW565C81019858

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modl : NII / S/Rlm / STD A/Rlm or _____

Tyre Size: F: 245/40ZR18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front		Rear	
R/Bal.	6 mm	R/Bal.	4 mm
L/Bal.	6 mm	L/Bal.	4 mm
D.O.A.	9/7/18	D.O.I.	23/7/18

Survey held at ✓

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
24/7	File pass to Catherine
30/8	LLp 8350 Confirm by email (Rec 4641.60, 36%)

RECEIVED 30 AUG 2018

Date/Time, File Pass to?

1) _____

Date/Time, File Return to?

2) 30/8 - typist

☐ : Prell. Report

☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp ($) ☐ : Interview ($) ☐ Tech Invs ($) ☐ Weekend ($)

Survey Fee: _____

Transportation: ___ $ + RS ___ SI

Photos _____

Others _____

TOTAL 350

Report Format : TP

Lump Sum / I.B.I: ($ 8350/2)

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Ref : CS/EGI18012742/Kvd3

Date : 13-07-2018

Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

	Insured Veh.	GBG 8186J	Veh. Inspected	EZ 4428C
	Policy No.		Coverage ($)	0.00
	Claim No.	DSMCV1801347/SL/pl	Excess ($)	0.00
	Assign From	YEE PEI LI	Assign Date	13/07/2018

2. Vehicle Particulars & Condition

	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			

3. Conditions of Tyres

		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

4. Description of Damages

5. General Information

	Accident Date	09/07/2018	Inspection Date	23/07/2018
	Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

LKK Auto Consultants Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DSMCV1801347/SL/pl
Our Ref: CS/EGI18012742/Kvd3

Without Prejudice

The Motor Claims Department
ERGO Insurance Pte Ltd

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. EZ 4428C .

We thank you for the instruction on 13/07/2018.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23/07/2018 at the premises of M/s LAI HUAT(MENG KEE) PTE LTD and have the following to report:-

Workshop Estimate Amount	: S$ 12,991.00 .
Revised Estimate Amount	: S$ 11,365.30 .
"Check" Items Amount	: S$ 1,536.30 .
Market Value	: S$.
LTA Reimbursement Value	: S$.
Nett Value	: S$.

Description of Damage:
The vehicle sustained damages at the rear portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully

KENNETH KONG
Automotive Assessor

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Friday, 13 July 2018 9:46 AM
To: 'admin-d@lkkauto.com'
Cc: ASSIGNMENTS@LKKAUTO.COM
Subject: OI : GBG8186J / TP : EZ4428C/LKK / DOA : 09/07/2018 (DSMCV1801347)
Attachments: GBG8186J - SAS.pdf; EZ4428C - SAS.pdf; EZ4428C - ESTIMATE.pdf; EZ4428C - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **LAI HUAT (MENG KEE) MOTOR PTE LTD**,

ADDRESS	:	BLK 160 SIN MING DRIVE #04-01 SIN MING AUTOCITY SINGAPORE 575722
PERSON TO CONTACT	:	JENNY @ 6453 8110
ERGO OFFICER-IN-CHARGE	:	STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and third party SAS **(note: reports not to be released to any Third Party).**

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
Tel : +65 6829 9199
Fax : +65 6829 9247
peili.yee@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 13.07.2018

Our Reference: DSMCV1801347/SL/pl

Your Reference: EZ 4428C

Sent via Fax: -

or

Email: jenny.lim@laihuat.com.sg

To: **LAI HUAT (MENG KEE) MOTOR PTE LTD**

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: **EZ 4428C**

Insured's Vehicle: **GBG 8186J**

Date Of Accident: **09.07.2018**

We acknowledge receipt of your request for PRS on: **12.07.2018**

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK Auto Consultants

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- [ ] Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
- [ ] Your request for inspection does not have your client's GIA report, kindly forward a copy.
- [ ] We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
- [ ] Our Insured's driver has not reported the accident to us todate.
- [x] Others: **OFFICER-IN-CHARGE - STEVE LIM**

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____

Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____

Time _____

Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

_____

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Wednesday, July 25, 2018 10:33 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR; 'Yee Pei Li'
Subject: RE: GBG8186J / TP : EZ4428C/LKK / DOA : 09/07/2018 (DSMCV1801347)
Attachments: EZ 4428C .pdf

Dear Sir,

Enclosed preliminary revised for **EZ 4428C**.

Thank you.

Best Regards,
Jannice Lee (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, July 13, 2018 9:54 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; 'Yee Pei Li' <peili.yee@ergo.com.sg>
Subject: RE: GBG8186J / TP : EZ4428C/LKK / DOA : 09/07/2018 (DSMCV1801347)

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,
G.Nivitha | Admin
LKK Auto Consultants Pte Ltd
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Friday, 13 July 2018 9:46 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: ASSIGNMENTS@LKKAUTO.COM
Subject: OI : GBG8186J / TP : EZ4428C/LKK / DOA : 09/07/2018 (DSMCV1801347)

Dear Catherine,

Veron Chen (LKKAuto)

From: Jenny Lim <jenny.lim@laihuat.com.sg>
Sent: Wednesday, 29 August 2018 3:01 PM
To: Kenneth Kong (LKKAuto)
Cc: SUR
Subject: Finalisation - EZ 4428C / Volvo V70
Attachments: EZ 4428C.pdf; IMG_1002.jpg; IMG_1003.jpg; IMG_1004.jpg; IMG_1005.jpg; IMG_1006.jpg; IMG_1457.jpg; IMG_1458.jpg; IMG_1459.jpg

Dear Sir

For your confirmation, please:

- Parts: $9,418.00
- L&P: $1,050.00

Sub-total: $10,468.00
LS -20%: ($2093.60) = $8374.40
Lump sum: $8350.00 / 8 days

Supporting document and photographs are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

来發（明记）嘩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No ..... : EST0019758
Tham Yew Chum

Page ..... 1 of 2
Your ref. ..... : TP-GBG 8186J ERGO
Job No ..... : 69650
Our ref ..... : 18.07.14
Payment .....
Date ..... : 23/7/2018

Not Without
Liab ?
Resurvey After Paint
4 days

Attn .....

Vehicle No .... : EZ 4428C
Vehicle Model . Volvo V70
Accident on ... 9/7/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
		Supply of Parts - Nett item:			
1.00	Pc	Rear bumper	1,754.80	Buf/Cut	1,754.80
1.00	Pc	Rear bumper lower	534.30	CM	534.30
1.00	Pc	Rear bumper top garnish	347.60		347.60
1.00	Pc	Rear bumper reinforcement	1,536.30		1,536.30
1.00	Pc	Rear parking sensor, centre LH	208.00	Short	208.00
1.00	Pc	Rear parking sensor, centre RH	208.00	Short	208.00
1.00	Pc	Rear tailgate	3,630.00	CM	3,630.00
1.00	Pc	Rear tailgate reflector LH	811.00	CM	811.00
1.00	Pc	Rear windscreen with moulding	2,433.60	Mdfy Adv	2,433.60
1.00	Pc	Rear V70 emblem	94.00		94.00
1.00	Pc	Rear T5 emblem	98.00		98.00
1.00	Pc	Rear Volvo emblem	102.00		102.00
1.00	Pc	Rear 2.5 emblem	94.00		94.00
		Labour & Misc:			
1.00		To dismantle and refix rear windscreen	160.00		160.00

Pr? NR

12 o/l

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發（明记）噂哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0019758
Tham Yew Chum

Page ..... 2 of 2
Your ref ..... TP-GBG 8186J ERGO
Job No 69650
Our ref 18.07.14
Payment .....
Date 23/7/2018

Attn .....

Vehicle No .. EZ 4428C
Vehicle Model . Volvo V70
Accident on .. 9/7/2018

Quantity	Unit	Description	Unit price	Disc pct	Amount
1.00		~~To supply~~ sealant	40.00		40.00
1.00		To transfer rear reversing camera + cables	60.00		60.00
1.00		To remove and renew above parts	280.00		280.00
1.00		To spray paint	600.00		600.00

Sub-Total		12,991.60
GST 7.00%		909.41
Total	S$	13,901.01

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發（明记）噻哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0019758
Tham Yew Chum

Page ..... 1 of 2
Your ref ..... TP-GBG 8186J ERGO
Job No 69650
Our ref 18.07.14
Payment .....
Date 23/7/2018

Not Authorised
Agree.
Liang ?
Ready After Paint
4 days

Attn .....

Vehicle No .... EZ 4428C
Vehicle Model : Volvo V70
Accident on ... 9/7/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
		Supply of Parts - Nett item:			
1.00	Pc	Rear bumper	1,754.80	Bull/cm	1,754.80
1.00	Pc	Rear bumper lower	534.30	CM	534.30
1.00	Pc	Rear bumper top garnish	347.60	M/	347.60
1.00	Pc	Rear bumper reinforcement	1,536.30		1,536.30
1.00	Pc	Rear parking sensor, centre LH	208.00	Shan	208.00
1.00	Pc	Rear parking sensor, centre RH	208.00	Shan	208.00
1.00	Pc	Rear tailgate	3,630.00	CM	3,630.00
1.00	Pc	Rear tailgate reflector LH	811.00	CM	811.00
~~1.00~~	~~Pc~~	~~Rear windscreen with moulding~~	~~2,433.60~~	~~M/~~	~~2,433.60~~
1.00	Pc	Rear V70 emblem	94.00	M	94.00
1.00	Pc	Rear T5 emblem	98.00	M	98.00
1.00	Pc	Rear Volvo emblem	102.00	M	102.00
1.00	Pc	Rear 2.5 emblem	94.00	M	94.00
		Labour & Misc.			
1.00		To dismantle and refix rear windscreen	160.00		160.00

Pr: Reuse.

120/

We remove it carefully

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大快修理，除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發（明记）噻哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0019758
Tham Yew Chum

Page ..... : 2 of 2
Your ref. ..... : TP-GBG 8186J ERGO
Job No. ..... : 69650
Our ref ..... : 18.07.14
Payment .....
Date ..... : 23/7/2018

Attn .....

Vehicle No . EZ 4423C
Vehicle Model . Volvo V70
Accident on . 9/7/2018

Quantity	Unit	Description	Unit price	Disc pct	Amount
1.00		To supply sealant	40.00		40.00
1.00		To transfer rear reversing camera + cables	60.00		60.00
1.00		To remove and renew above parts	280.00		280.00
1.00		To spray paint	600.00		600.00

Sub-Total		12,991.60
GST 7.00%		909.41
Total	S$	13,901.01

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Ref : CS/EGI18012742/Kvd3n2

Date : 03-09-2018

Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

	Insured Veh.	GBG 8186J	**Veh. Inspected**	EZ 4428C
	Policy No.		**Coverage ($)**	0.00
	Claim No.	DSMCV1801347/SL/pl	**Excess ($)**	0.00
	Assign From	YEE PEI LI	**Assign Date**	13/07/2018

2. Vehicle Particulars & Condition

	Make & Model	VOLVO V70 T5 (A)	**c.c**	2521
	Engine No.	HIDDEN	**Year of Reg.**	2008
	Chassis No.	YV1BW565081019858	**Colour**	METALLIC GREY
	Odometer	195749	**Steering**	IN ORDER
	Brakes	IN ORDER	**Modification**	STANDARD ALLOY RIM
	General	GOOD		

3. Conditions of Tyres

		Size	**Make**	**Balance**
	R/H Front Tyre	245/40 ZR18	MICHELIN	6 mm
	L/H Front Tyre	245/40 ZR18	MICHELIN	6 mm
	R/H Rear Tyre	245/40 ZR18	MICHELIN	4 mm
	L/H Rear Tyre	245/40 ZR18	MICHELIN	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

	Accident Date	09/07/2018	**Inspection Date**	23/07/2018
	Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EZ 4428C

Qty	Description of Parts	Condition	Estimate By Workshop ($))	Our Adjusted ($)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (SN)	BUCKLED / CRACKED	1,754.80	1,754.80
1	REAR BUMPER LOWER (SN)	CRACKED	534.30	534.30
1	REAR BUMPER TOP GARNISH (SN)	MISSING	347.60	347.60
1	REAR BUMPER REINFORCEMENT (SN)	BENT	1,536.30	1,536.30
1	REAR PARKING SENSOR,CENTRE LH (SN)	SHORTED	208.00	208.00
1	REAR PARKING SENSOR,CENTRE RH (SN)	SHORTED	208.00	208.00
1	REAR TAILGATE (SN)	CRACKED	3,630.00	3,630.00
1	REAR TAILGATE REFLECTOR LH (SN)	CRACKED	811.00	811.00
1	REAR WINDSCREEN WITH MOULDING (SN)	NOT NECESSARY	2,433.60	-
1	REAR V70 EMBLEM (SN)	NECESSARY	94.00	94.00
1	REAR T5 EMBLEM (SN)	NECESSARY	98.00	98.00
1	REAR VOLVO EMBLEM (SN)	NECESSARY	102.00	102.00
1	REAR 2.5 EMBLEM (SN)	NECESSARY	94.00	94.00
1	SEALANT (SN)	NECESSARY	40.00	40.00
			11,891.60	9,458.00
	LABOUR			
	TO DISMANTLE AND REFIX REAR WINDSCREEN.		160.00	120.00
	TO TRANSFER REAR REVERSING CAMERA + CABIES.		60.00	60.00
	TO REMOVE AND RENEW ABOVE PARTS.		280.00	280.00
	TO SPRAY PAINT.		600.00	550.00
			1,100.00	1,010.00
	GRAND TOTAL		**12,991.60**	**10,468.00**

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			**8,350.00**

Report Ref No. CS/EGI18012742/Kvd3n2

KSC

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.