CITY CAB PTE LTD

REPAIR ESTIMATE*

AXA-4S

TS

1130

VEHICLE NO : SHC 296C **DATE 16/7/2018**

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover — cra			$ 538.80	
	Front Bumper Sponge Xsu			$ 136.30	
	Front Bumper Reinforcement Xsu			$ 504.10	
	Front Bumper Bracket Top (RH) Xsu			$ 22.40	
	Front Bumper Protector (RH) Xrepair			$ 29.20	
	Headlamp (RH) — grazed			$ 797.90	
	Front Fender (RH) — Rd			$ 593.00	
	Front Fender Shield (RH) Xsu			$ 86.00	
	Front Wheel Rim (RH) Xsu			$ 284.70	
	Front Wheel Hub Cap (RH) — bra			$ 145.00	
	Front Bonnet Xrepair				
	SUB TOTAL			**$ 3,137.40**	
	LESS 20%			$ 627.48	
	DISCOUNTED TOTAL			**$ 2,509.92**	
	Front Fender Advertisement Logo (RH) — nu			$ 100.00	**Nett**
				$ 100.00	
	Labour Charge				
	Panel Beating			$ ~~560.00~~ 400	
	Spray Painting Charge			$ ~~600.00~~ 540	
	Wiring Charge			$ ~~50.00~~ 20	
	Tuff Kote			$ ~~50.00~~ 20	
	FRT Wheel Alignment			$ ~~80.00~~ Xn	
	TOTAL LABOUR			**$ 1,340.00**	
	ESTIMATE TOTAL			**$ 3,949.92**	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kalin 16/7

16/7/18 1410 hrs

2 days

4S

After Repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.