22/02/2002

ASS. REC. BY: | REF: CS3/EGI18012920/T1z4d3 | Special Instruction:

Surveyor: Tauhfiech

ASSIGNMENT (Office)

From (Person): Yee Pei Li of EGI Date/Time: 17/7/18 @ 9.13am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBD 4U Insured: SDR 333C

at Workshop m/s Seng Huee Motor Tel: 6755 5205

of Blk 101B, Yishun Ind. Park A #01-350

Policy No: SDR 333C Claim No: ~~SDR 333C~~

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 13/07/2018

CA / REV / REP. / REV 24 HRS 'up)

Date/Time: 9.21am @ 17/7/18 Person Contacted: Mr. Kuch H.O.D. Endorsement: Vehicle: IN / OUT

Date/Time	Action/Instruction
	(X) Estimate
	GBD 4U - X
	SDR 333 C - X
	After repair: 20/7/2018.

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up)

Vehicle: IN / OUT

Date: Person Contacted:

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 17/7/18 @ 330

Survey held at ~~KALPOS~~ Seng Huee Motor.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Estimated repair range $3,500 – $4,000
1/8	Submit PRS report. 1/8/18

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format : PRS

Lump Sum / I.B.I: ($)

Survey Fee:

Transportation: ___S + RS, ___SI

Photos

Others

TOTAL