Allswell Motor Traders

25 Defu Lane 9. Singapore 539266
Tel : +65 6679 1146 email:ben@allswellmotor.com.sg

(3rd party claim against AXA Insured SKK2860H)

Estimate repair

Vehicle No.	: SLP 5672B	Submitted by	: Ben
Make & Model	: Toyota Prius	COE expiry	: 08-06-2027
Chassis No.	: hybrid.	Engine No.	:
Date of survey	:		

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01	RH rear corner panel / RR	01	$169.9		
02	Rear bumper X repair.	01	$1,219.0		* repaired
03					
			25% :	127.43	
	Labour description				
01	Dismantle / Assembly of rear bumper corner panel including make good of RH mudshield	01	$260.0	200	
02	Spray painting of all affected part including putty, sand paper polishing wash	01	$660.0	250	
				577.43	
	2Days.				
	part by part.				
	before paint photos.				
	Guo Qing				
	03/8/18.				

LKR Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.