PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443
TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

6-Aug-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8957 G

1 pc	Bootlid emblem	$	27.00
1 pc	Bootlid CRDi	$	29.00
1 pc	End panel × repair	$	250.00
1 pc	End panel garnish ?	$	74.00
1 pc	Rear bumper	$	696.00
1 pc	Rear bumper lower cover	$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ $29.00 ?	$	58.00
1 pc	Rear bumper inner sponge	$	114.00
1 pc	Rear bumper reinforcement	$	607.00
2 pcs	Rear bumper stay n/s & o/s @$53.00 ?	$	106.00
2 pcs	Rear bumper reinforcement lower bracket @ $18.00 ?	$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ $18.00 ?	$	36.00
2 pcs	Rear o/s & n/s bumper reflector @$46.00 ×	$	92.00
		$	2,331.00
	Less 10%	$	233.10
		$	2,097.90

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kalin Clerk
6/8/18 13 inches
4 Days
L/S
After Repair photo

S/NETT

1 set	End panel inner garnish clips ×	$	20.00
1 set	Bootlid stickers	$	100.00
1 set	Reverse sensor	$	~~200.00~~ 200
	Sundry	$	~~50.00~~ 20
	To dismantle / replace reverse sensor to new bumper and reset to the same	$	~~80.00~~ 30
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	$	~~60.00~~ ×
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld cut-off the end panel. Including knock-out, straighten, repair, reshape and adjust of the floorboard compartment, bootlid, etc	$	~~850.00~~ 600
	To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel, floorboard compartment ×	$	~~1,100.00~~ 720
	To apply rustproofing on the repaired and replaced panels.	$	~~200.00~~ ×
		$	4,757.90

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.