ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
GREAT AMERICAN INSURANCE COMPANY 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190 Motor Claims-Mr Michael Tay Contact No 68046037	Cust No/Name	KCVO5808/Mr Zailan Bin Mustaffa
	Reg No/Reg Date	SLF7868T / 09/09/2016
	Date In/Mileage	28/08/2018/ 0
	Chassis No	JMYXTGF3WGZ003831
	Engine No	4B12RL6146
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (G43)
	Colour/Trim	PO2 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000087	Credit	10/09/2018/ 08:19	Bod	323 / ChrisBulaclac	62791

	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X JJMR288150	CLIP,RR BUMPER	10.00	3.00	0.00	30.00
X JJMR328954	CLIP,SPLASH SHIELD _Nᴇᴡ_	10.00	4.00	0.00	40.00
X JJMR590000HB	CLIP SKID	5.00	3.00	0.00	15.00

Adrian Ling

Estimate

supplementary item

Confirm & accepted by		
	Parts	85.00
	Labour	0.00
	Standard Menu	0.00
	Specialist Job	0.00
	Others(Lub,etc)	0.00
	Sundry	0.00
Authorized signatory and company stamp	Total(w/o GST)	85.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.