(08/11/13) wef

ASS. REC. BY:

REF: III

ASSIGNMENT

From: Date: 04092018

Estimated Cost:

OD / TP / AWS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLG 8283T

at Workshop m/s Kah motor

of 15 Ubi Rd 4

Insured:

Policy No. -

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Any

(Policy Condition) after 10.30am

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLG8283T. Yr Regn: 2016 / Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Civic c.c 1498

Colour Grey. A/C: Insured / Std / NI / NA

Sp.Reading 35850. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MRHCF1660GT000131.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/50R17.

R: 215/50R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.		D.O.I.	04/09/18

Survey held at Kah Motor

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Pg 111

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:

Transportation: __S + RS, __SI

Photos

Others

TOTAL