LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveyors on a "without prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:
Mr Nguyen Ngoc Thanh Liem

AXA Insured's Veh No : PA4493P
Date of Accident : 28 September 2018

not billed
LKK
L/S $3900/2
Telephone Attorney
3/10/18
4 days.

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD
51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Date : 03 October 2018

LKK – marcus
03/10/18 @ 1500hrs

Estimate To Repair SKG4195C - Audi A4 1.8 TFSI MU
Chassis No : WAUZZZ8K1DA065704

S/No	Quantity	Description	Amount	
		LIST ITEMS		
01	1 pc	left headlamp SCR	$ 1,642.50	
02	1 pc	left headlamp top mount bracket 11	$ 70.00	
03	1 pc	front bumper DE/repair	$ 1,898.00	
04	1 pc	front bumper side retainer left SCR	$ 34.00	
05	1 pc	front bumper spot lamp left 11	$ 194.10	
06	1 pc	front bumper spot lamp garnish left 11	$ 125.85	
07	1 pc	front bumper lower splasheid cover 11	$ 677.70	
08	1 pc	front bumper absorber foam 11	$ 57.00	
09	1 pc	left front fender Bods DE/repair	$ 711.25	
10	1 pc	left front fender inner liner	$ 119.25	
11	1 pc	left front wheel rim DE/repair	$ 1,156.25	
12	1 pc	left front shock absorber 11	$ 1,437.85	
13	1 pc	left front lower arm 11	$ 1,003.25	
14	1 pc	left front upper arm 11	$ 540.20	
15	1 pc	left front torsion arm 11	$ 960.00	
16	1 pc	left front wheel knuckle 11	$ 1,020.55	
17	1 pc	left front wheel bearing with hub 11	$ 497.35	
			$ 12,145.10	
		Less 10 % 502	$ 1,214.51	
			$ 10,930.59	
		SPECIAL NETT ITEMS		
18	1 pc	left front wheel tyre SCR	$ 550.00	
			$ 550.00	
		LABOUR & MISC. CHARGES		
01		To check electrical lighting concerned.	$ 80.00	20
02		To rust-proofing of the affected areas.	$ 100.00	30
03		To check steering geometry and computer wheel alignment.	$ 120.00	380
04		To transfer of tyre, rim and on wheel balancing.	$ 50.00	
05		To drop front suspension undercarriage parts, remove and renewal of the necessary parts, to perform final checking and testing.	$ 11 350.00	400
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	$ 700.00	600
07		Putty and spray painting of the affected portion.	$ 950.00	1130
			$ 2,350.00	
		Total	$ 13,830.59	

1-561.25
582
278062
1130
3910

L/sum $3900 x 4 days
commd 03/10/18