TOYOTA

Borneo Motors (Singapore) Pte Ltd
Online Service Booking :
www.toyotasingapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

leg No : 196700086Z
Reg No : MR-8500000-9

ESTIMATE

Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1 Document No 0 Document Date 12/10/2018	M/s Borneo Motors (Singapore) Pt 2 Pandan Crescent Inchcape Centre Singapore 128462 Work: 64751288

ar	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
AWXEBW S1		ZVW40R	14/02/2018	SLW4999D	0	36464	60D/SLW4999D/12101:

hassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
DZS3EU20J020419	2ZR0A13700		60	Shashitharan	--/--/---- 0.00	--/--/---- 0.00

	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: B290891136MCY ACC DATE:11/10/18 DRIVE IN:11/10/18 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50 ~~100.00~~
2	B	BP-LAB CHECK WIRING AND CONDUCT LEAK TEST				169.50
3	B	BP-LAB TRANSFER DOOR MECHANISM				339.00
4	B	BP-LAB R/I SIDE TRIMMING TO FAC REPAIR				339.00
5	Z	BP-SLANT SUPPLY SEALANT (NETT) 2 PANEL				~~169.00~~ 80
6	B	BP-LAB REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALLIGN ACC AFF AREA				1356 ~~2712.00~~
7	B	BP-RES RESRPAY ACC AFF AREA				1668 ~~1875.20~~
8	B	BP-MECH RESET ECU UPON COMPLETION OF REPAIR				169.50
9	1	T61602-47130 PANEL SUB-ASSY,	1.00	926.90	15.00	Pt ~~787.86~~
10	2	T58742-47020 PROTECTOR, QUARTER	1.00	22.60	15.00	~~19.21~~
11	3	T67004-47180 PANEL SUB-ASSY, RR	1.00	1258.30	15.00	repair ~~1069.55~~
12	4	T75924-47030 TAPE, BLACK OUT,	1.00	47.10	15.00	~~40.03~~
13	5	T75988-47050 STRIPE, RR DOOR,	1.00	25.70	15.00	~~21.84~~
14	6	T75978-47050 STRIPE, RR DOOR,	1.00	21.40	15.00	~~18.19~~

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less Amount Due

3776349

PLEASE TEAR ALONG PERFORATED LINE

3776349

O SECURITY GUARD

DATE 12/10/2018
TIME 11:18

LEASE ALLOW THE UNDERMENTIONED
EHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLW4999D

SIGNATURE
FOR *BORNEO MOTORS (SINGAPORE) PTE LTD*

Inchcape Borneo Motors

USTOMER

Nature Of Damage:

No. Of Passenger (Including Driver):

Surveyor's Copy

ASSIGNMENT

00862

From: Date: Veh No: SLW 4999 D

TOYOTA

No : 196700086Z
g No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd
Online Service Booking :
www.toyotasingapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

yota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1 Document No 0 Document Date 12/10/2018	M/s Borneo Motors (Singapore) Pt 2 Pandan Crescent Inchcape Centre Singapore 128462 Work: 64751288

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	AWXEBW S1	ZVW40R	14/02/2018	SLW4999D	0	36464	:60D/SLW4999D/12101:

Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
JTDZS3EU20J020419	2ZR0A13700	60	Shashitharan		--/--/---- 0.00	--/--/---- 0.00

L	Cd	Job/Parts Description		Qty	Unit Price	Disc %	Amount
15	7	T75989-47060	STRIPE, RR DOOR,	1.00	21.40	15.00	Rep 18.19
16	8	T67872-47040	WEATHERSTRIP, RR	1.00	176.00	15.00	Rep 149.60
17	9	T75860-47020 C2	MOULDING ASSY, BODY	1.00	981.90	15.00	SOR 834.61
18	0	T76924-47020	RETAINER, SIDE	1.00	5.10	15.00	Rep 4.33
19	1	T76923-47010	RETAINER, SIDE	1.00	10.60	15.00	Rep 9.01
20	2	T65632-47060	PLATE, RR WHEEL	1.00	46.80	15.00	39.78

Rasul
Hp 90010068
6 days
15/10/18 @ 09:30
EXCESS : 1500
Repair
Resurvey by paint

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary		Total	8,876.40
	Please acknowledge receipt of vehicle	Parts	3,012.20	GST 7.00%	621.35
		Labour	5,864.20	Less	0.00
		Materials	0.00		
		Lubrication/Fluid	0.00		
		Others	0.00	Amount Due	9,497.75

3776350

PLEASE TEAR ALONG PERFORATED LINE

3776350

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 12/10/2018
TIME 11:18

VEHICLE NO SLW4999D

Borneo Motors