COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

QBE - (P/P)

TS

VEHICLE NO : SHC 1079G **DATE 13/10/2018**

MAKE :

MODEL : HYUNDAI IONIQ - G2

LKK - Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover			$ 418.30	
	Front Bumper Grille (LH)			$ 186.90	
	Day Light			~~$~~	
	Front Bumper Bracket (LH)			$ 28.00	
	Headlamp (LH)			$ 1,198.80	
	Front Fender (LH)			$ 490.70	
	Front Wheel Hub Cap (LH)			$ 346.40	
	SUB TOTAL			**$ 2,669.10**	
	LESS ~~20%~~ 25%			$ 533.82	
	DISCOUNTED TOTAL			**$ 2,135.28**	
	Emblem-Blue Drive (LH)			**$ 26.60**	**Nett**
	Kalvin / LKK 15/10/18 1130 hrs 3 Days. P/P Before Paint photo				
	Labour Charge				
	Panel Beating			$ ~~440.00~~ 400	
	Spray Painting Charge			$ ~~440.00~~ 400	
	Wiring Charge			$ ~~30.00~~ 20	
	Tuff Kote			$ ~~50.00~~ 20	
	FRT Wheel Alignment			$ ~~120.00~~ x	
	Tow Charge - King Dolly			~~$ 150.00~~ 100	
	TOTAL LABOUR			**$ 1,080.00**	
	ESTIMATE TOTAL			**$ 3,241.88**	

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

(R14)

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.